


FACTS AND FIGURES



Damage Grade (1-2)
347

Damage Grade (3-5)
2,668

Damage Status - Private Structures

MAJOR HOUSING TYPOLOGIES

Typology	Municipal	District
Adobe Structures	46.93%	58.15%
Brick and Mud Mortar Masonry	37.52%	21.70%
Brick and Cement Mortar Masonry	8.74%	4.96%
Reinforced Cement Concrete (RCC) Frame	3.16%	2.94%
Others	3.65%	12.26%

CBS damage assessment survey, 2015

HOUSING RECONSTRUCTION & RETROFIT UPDATES

Reconstruction Status

Total Eligible HHs	2,333
PA Agreement	2,060
I st Tranche received	2,060
II nd Tranche received	681
III rd Tranche received	638

Houses

Under Construction: -

Completed: -

Retrofitting Status

Total Eligible HHs	101
PA Agreement	56
I st Tranche received	56
II nd Tranche received	101

Grievances

Registered: 2,407

Addressed: 1,431

Non-compliances

Registered: -

Addressed: -

Data Updated on: 2019-05-17 00:00:00

P0 Presence

Active: No POs Reported

Phased Out: GON (Shelter) , ISAP (Shelter)

STATUS OF CONSTRUCTION MATERIALS

Materials	Unit	Req. Quantity*	Ava.	Cost (NRs.)**
Stone	m ³	40,774	-	-
Aggregate	m ³	30,870	-	-
Sand	m ³	4,251	-	-
Timber	cu. ft.	4,529	-	-
Cement (PPC)	Sack	-	-	-
Cement (OPC)	Sack	103,667	-	-
Rebars	kgs.	457,939	-	-
Tin	bundle	4,218	-	-
Bricks	pcs.	1,144,788	-	-

Types of Workers

1. Skilled mason
2. Labourer

Avg. daily wage (NRs.)

- / -
- / -

OTHER SECTORS



Schools

Damaged: 7
Under Construction: 3
Construction Completed: 3



Health Posts

Damaged: -
Under Construction: -
Construction Completed: -

KEY CONTACTS

Municipal Office
Madan Sundar Shrestha
Mayor
9851201305

Municipal Office
Anugya Pant
Focal Person
9841342353

Municipal Office
Anjana Devi Madhikarmi
Deputy Mayor
9851201304

GMaLI/NRA
Dhruba Gaida
NRA Chief-District
9851221570

Municipal Office
Kamal Gnawali
Administration Officer
9851027566

DLPIU-Building
Mahalaxmi Joshi
DUDBC.DLPIU Chief
9751090249

HHs WITH LAND ISSUES

No Reported Land Issues

STATUS OF TECHNICAL STAFF


Staff	Available Nos.	Additional Req. Nos.
Engineers	8	1
Sub-Engineers	8	-
Asst. Sub-Engineers	1	1
Masons	- (7 days) - (50 days)	- (7 days) 170 (50 days)

Source: Municipal survey

MASON TRAINING


Trainings (# out of total required)

7 days Training



Reached


50 days Vocational Training



Remaining

Source: HRRP Analysis

TA ACTIVITIES MAP



FAQs

Q: What documents are required for enrolment in the GoN housing reconstruction programme?

A: Two copies of passport size photos and original copy and photocopy of land ownership card and citizenship card. Local officials at the Rural / Urban Municipality will be able to provide information and support and households can enrol at the Rural / Urban Municipality.

Q: Do we need to pay the engineers when they come to conduct inspections or provide technical assistance?

A: No, you do not have to pay the engineers, or any other staff, conducting inspections or providing technical assistance. If any field staff request payment for conducting inspection or providing technical assistance you should report it to the Rural / Urban Municipality officials.

For further information 1. Ambika Amatya (District Coordinator) 9841356409 2. (District Technical Officer) 0 3. Sachin Malego (District Information Management Officer) 9849166793