


FACTS AND FIGURES



Damage Grade (1-2)
654

Damage Grade (3-5)
5,481

Damage Status - Private Structures

MAJOR HOUSING TYPOLOGIES

Typology	Municipal	District
Stone and Mud Mortar Masonry	97.98%	69.19%
Adobe Structures	1.57%	15.32%
Stone and Cement Mortar Masonry	0.13%	0.29%
Bamboo	0.13%	0.11%
Others	0.21%	15.09%

CBS damage assessment survey, 2015

HOUSING RECONSTRUCTION & RETROFIT UPDATES

Reconstruction Status

Total Eligible HHs	6,417
PA Agreement	5,560
I st Tranche received	5,610
II nd Tranche received	4,306
III rd Tranche received	3,152

Houses

Under Construction: -

Completed: -

Retrofitting Status

Total Eligible HHs	442
PA Agreement	46
I st Tranche received	46
II nd Tranche received	442

Grievances

Registered: 1,578

Addressed: 1,517

Non-compliances

Registered: -

Addressed: -

Data Updated on: 2019-05-15 00:00:00

P0 Presence

Active: No POs Reported

Phased Out: CARITAS-N (Agriculture), CARITAS-N (DRM), CARITAS-N (Shelter), GON - DUDBC (Shelter), NN (Shelter), NRCS (Health), NYF (Education), NYF (Shelter), SABAL (Shelter), Tdh (Health)

STATUS OF CONSTRUCTION MATERIALS

Materials	Unit	Req. Quantity*	Ava.	Cost (NRs.)**
Stone	m ³	61,968	Y	5,000
Aggregate	m ³	64,939	N	35,000
Sand	m ³	6,629	N	35,000
Timber	cu. ft.	7,694	Y	-
Cement (PPC)	Sack	-	N	-
Cement (OPC)	Sack	214,341	N	-
Rebars	kgs.	668,867	N	-
Tin	bundle	8,758	N	-
Bricks	pcs.	418,941	N	-

Types of Workers

1. Skilled mason
2. Labourer

Avg. daily wage (NRs.)

1,200 /-
1,000 /-

OTHER SECTORS



Schools

Damaged: 55
Under Construction: 10
Construction Completed: 10



Health Posts

Damaged: -
Under Construction: -
Construction Completed: -

KEY CONTACTS

Municipal Office

Dina Nath Gautam
Mayor
9751003030

Municipal Office

Pramila Gautam
Focal Person
9849155842

Municipal Office

Tara Chaulagain
Deputy Mayor
9865051558

GMaLI/NRA

Lok Nath Regmi
NRA Chief-District
9851146403

Municipal Office

Kuber Nagarkoti
Administration Officer
9813439944

DLPIU-Building

Mahalaxmi Joshi
DUDBC.DLPIU Chief
9751090249

HHs WITH LAND ISSUES

63

Landless

STATUS OF TECHNICAL STAFF


Staff	Available Nos.	Additional Req. Nos.
Engineers	5	-
Sub-Engineers	9	-
Asst. Sub-Engineers	9	-
Masons	110 (7 days) - (50 days)	0 (7 days) 100 (50 days)

Source: Municipal survey

MASON TRAINING


Trainings (# out of total required)

7 days Training



Reached


50 days Vocational Training



Remaining

Source: HRRP Analysis

TA ACTIVITIES MAP



FAQs

Q: What documents are required for enrolment in the GoN housing reconstruction programme?

A: Two copies of passport size photos and original copy and photocopy of land ownership card and citizenship card. Local officials at the Rural / Urban Municipality will be able to provide information and support and households can enrol at the Rural / Urban Municipality.

Q: Do we need to pay the engineers when they come to conduct inspections or provide technical assistance?

A: No, you do not have to pay the engineers, or any other staff, conducting inspections or providing technical assistance. If any field staff request payment for conducting inspection or providing technical assistance you should report it to the Rural / Urban Municipality officials.

For further information 1. Reshma Shrestha (District Coordinator) 2. (District Technical Officer) 3. Ishor Neupane (District Information Management Officer)
9841264190 9801317265