

District Report

Dhading

25 May - 7 June 2018

Activity Summary

Activity	Contact Person	Reference Document
Field visit at Ruby Valley rural municipality from 21-26 May	dc.dhading@hrrpnepal.org techcord.dhading@hrrpnepal.org awasthikr@gmail.com	For detail, please refer to – field visit section.
Public hearing program organized by Transparency International-Dhading at Dhunibesi municipality on 5 June	dc.dhading@hrrpnepal.org techcord.dhading@hrrpnepal.org	For details refer news & update section.
HRRP Hub-meeting at Siddhartha hotel from 5-8 June	dc.dhading@hrrpnepal.org techcord.dhading@hrrpnepal.org	
Regular visits with partner organizations of the district.	dc.dhading@hrrpnepal.org techcord.dhading@hrrpnepal.org	
Collection of mason training data and recording on HRRP training database.	techcord.dhading@hrrpnepal.org	

Upcoming Events & Meetings

Event / Meeting	Date, Time, and Location	Contact Person
Orientation program on “Light Timber/steel Frame Structure Manual”.	13 th June 2018 at Dhadingbesi, Hotel R.K., Dhading.	dc.dhading@hrrpnepal.org techcord.dhading@hrrpnepal.org
To include details of upcoming events and meetings in the next bulletin, please share details with dc.dhading@hrrpnepal.org by COB Wednesday of each week.		

News & Updates

“Public Hearing at Dhunibesi Municipality organized by Transparency International Nepal on 5th June 2018.”



Photo: Public hearing program on reconstruction activity with general public and government stakeholders.

At the public hearing program, Transparency International Nepal invited all relevant stakeholders who are directly concern with the current reconstruction activities with the district. Many of the public were gathered at the program in order to get the answers out of the government authorities live and face to face.

During the event there were mayor of Dhunibesi municipality, Division Engineer of DUDBC, NRA chief, ward leaders, representatives of banks, NRA field engineers, HRRP and POs working at Dhunibesi municipality. Many of the participants of the program focused on the result of the grievance registered through ward offices. The key concern was when will the result be published from NRA.

Some of the issues were raised regarding non-compliance cases, where people had built houses just after the earthquake when no any NRA guidelines were published. In such situation, how would they be eligible to receive further tranches and what will be the process. To address this issue, DE from DUDBC suggested to conduct structural analysis at the district or one could also perform this analysis on his own through private hiring of structural engineers on one's effort. Thus, the outcome of the analysis would decide whether he/she is eligible to receive 2nd and 3rd tranches from the government.

Field Visit Reports

Date:	Location	Participants
May (21 st – 26 th) 2018	Ruby Valley Rural Municipality, Ward no.: 1 & 2.	• Khagendra Awasthi (MOUD-CLPIU, M&E) • Prabin Gautam (HRRP/CRS) – DC • Pradip Sharma (HRRP/NSET) – DTC
Objective(s)	• Joint monitoring visit with MOUD-CLPIU • To know the current progress status of reconstruction • Community involvement in reconstruction and their challenges. • Coordinate with the municipality for Information management training. • Reconstruction Update/ Housing Reconstruction Challenges • Sharing of Information about Reconstruction to newly elected members • Interaction between government agencies, implementing partners and local people • Collection of Typologies of Houses	
Summary	<u>Reconstruction Update/ Housing Reconstruction Challenges</u> Joint visit was conducted by HRRP Dhading along with MOUD-CLPIU M&E (Khagendra Awasthi). The field visit gave an opportunity to MOUD-CLPIU and HRRP to observe, supervise and monitor ongoing construction of Houses (Compliance & Non-Compliance houses) at Tipling VDC. The number of beneficiaries in Tipling VDC are 768 among them 767 received the first Tranche while 408 beneficiaries are approved for second Tranche while 227 beneficiaries are approved for third Tranche. In Tipling Vdc, most of the houses are Load bearing structures (Stone Masonry in Cement/Mud Mortar). The Constructed houses are Stone Masonry with Cement Mortar, timber framed structure, Mixed structure (Stone masonry with mud/ cement mortar in Ground Floor while light materials like CGI Sheet in First Floor, Timber in timber frame structure). Some of the Key points that make Tipling a good compliant VDC • Availability of Local Material i.e. Stone, Timber, Sand etc. • Availability of Mason, Skilled & Un-skilled manpower. • Skilled Manpower = 1000 • Un-Skilled Manpower = 9000 Housing Reconstruction Challenges in Tipling: • Lack of monitoring of trained masons at their locality. • Door to door technical Assistance is insufficient • Challenge in transportation of construction materials at most of the areas of Dhading. • Unavailability of government engineers for technical support to beneficiaries at rural municipalities. • NRA lengthy approval process (community buildings, mason trainings, Shelter). Sharing of Information about Reconstruction to newly elected members The visit provided opportunities to share Information to newly elected members & DLPIU Engineers. During the visit, We suggest DLPIU Engineers to make local	

people aware of using earthquake resilience techniques. We shared soft copy, orient them to use manual. The challenges and reconstruction progress were also shared. VDC wise Enrolment status, District Profile, NRA Policy & guidelines, Info Pack etc. are being shared and discussed with the newly elected members.

Interaction between government agencies, implementing partners and local people
The visit provided opportunities to agencies to raise queries and verify them. Local people also got involved in the interaction and did bilateral talks. During the visit, we suggest local people to use earthquake resilience techniques that are available through NRA and seek help from various organizations working at the locality.

- The field visit was important because it reflects the real scenario/situation of the field and people living at such area.
- HRRP in close coordination with Partner organization, DLPIU engineers provided opportunities to observe, listen and give appropriate suggest to the beneficiaries.

Collection of Typologies of Houses

During the field visit housing typologies of newly constructed and on-going houses were collected. The typologies were collected from Tipling VDC. The major factors affecting the typology of the houses were Availability of Manpower, Social-need Economic conditions, tradition, prevailing condition etc.

Housing Typology Report



The house located at Tipling VDC - 01, Dhading Phatta Ghale, the house owner, had received first and second Tranche and processing for Third Tranche. It is a single room of Load Bearing Building and one storey with CGI sheet roofing.

Key Points :-
Stone Masonry in mud mortar



Shree Ghale, residence of Tipling VDC-01, Dhading had received first Tranche and got approved for second tranche too.

Key Points :-
Load Bearing Structure
Tie Beam provided
Sill Band
Lintel Band
At gable wall light material
one storey with CGI sheet roofing.



Suppa Tamang Tamang, residence of Tipling VDC -01, had constructed a Load Bearing Structure (Dry Stone Masonry
1 storey building
Get 1st tranche
Processing to get 2nd tranche.



Loho Bahadur Tamang, residence of Kiranchok VDC, is constructing a Load Bearing Structure (Stone masonry in Cement Mortar. He received first tranche and got approved for second tranche too.