

District Report

Kavrepalanchok

20 July – 2 August 2018

Summary of events during this period

Name of activity/event	Event date	Participants summary		Contact Person	Reference Document
		Male	Female		
Orientation on NRA 5W Reporting	19 th July 2018	6	1	im.kavrepalanchok@hrrpnepal.org	Report
HRRP Summary Report to GMALI, DUDBC/DLPIU	20 th July 2018	-	-	reshma@hrrpnepal.org	Report
Field visit to RyaleBhir, Panauti (Objective: For case studies on One Room structures.)	23 rd July 2018	1	1	reshma@hrrpnepal.org	Details in the field visit section below
Meeting with GMALI (Objective: To discuss on need of orientation to the ward officials on moving forth with enrolment after the Resurvey and Reverification results.)	24 th July 2018	4	1	reshma@hrrpnepal.org	NA
5W Update	25 th July 2018	-	-	im.kavrepalanchok@hrrpnepal.org	Google Drive
Support to GMALI (Data entry, grievance handling)	Ongoing	-	-	reshma@hrrpnepal.org	NA

Upcoming Events & Meetings

Name of activity/event	Date, Time, and Location	Organizer	Contact Person
Joint Monitoring Field Visit to Roshi Gaupalika	7 th -10 th August 2018	HRRP Kavre	reshma@hrrpnepal.org
GMALI/HRRP Coordination Meeting	13 th August 2018	HRRP Kavre	reshma@hrrpnepal.org
Orientation to Ward Officials on "Procedures of enrolment for beneficiaries identified from Resurvey and Reverification"	TBC	GMALI/CARITAS/HRRP	reshma@hrrpnepal.org
To include details of upcoming events and meetings in the next bulletin, please share details with reshma@hrrpnepal.org by COB Wednesday of each week.			

Field Visit Report

Visit 1

Date	Location	Participants from HRRP and stakeholders
23 rd July 2018	Ryalebhir, Panauti Municipality 1	• Reshma Shrestha • Ishor Neupane

Objective(s)

- For case research on One Roomed Houses.

Summary

A total of 50 one roomed houses have been constructed across RyaleBhir, Panauti Municipality Ward 1. Amongst the 50, 10 have received second tranche and been inspected for the third with files still pending whereas for the remaining 40, the files for second tranche are pending at DUDBC/DLPIU. (Source: DLPIU engineer, Ward Chief).

As per the DLPIU engineer, all of the one roomed houses exceed an area of 150sq.ft. (minimum area defined is 120sq.ft.) and fit into the area standards as per the correction and exception manual. Most of these houses were started before the Paush benchmark was issued for one roomed house stating only vulnerable beneficiaries can proceed with tranche applications for such structures along with the consent letter from the ward and thus, failed to apply for the third tranche before Paush.

During the visit, eight houses were visited and the beneficiaries were briefly interviewed on the reasons for constructing one roomed house. All of the beneficiaries still inhabited the pre earthquake house and none have carried any major repairs in their pre earthquake house. The majorly reported reasons for constructing one roomed structures were:

- Reluctance to demolish pre earthquake house
- Sloped terrain and smaller plots of land available
- Hesitance to leave the place of origin and migrate to available appropriate land in other wards
- Optimism on being eligible for further tranches for the one room structure in due course of time.

Regarding the usage of the one roomed houses, the beneficiaries were positive in fitting some of the livability functions in the house in due course rather than solely using it as sheds and storage.

Challenges / Issues Identified	Action Required	Responsible	Timeframe
Continued/Increased risks from the hugely damaged pre earthquake houses	Strategies to encourage beneficiaries to either demolish or retrofit the risky pre earthquake houses	NRA	Soon

Photos



The new earthquake houses amidst the still tall pre-earthquake houses at RyaleBhir, Panauti Municipality, Ward 1.



The largest possible one room house compliant as per Correction and Exception Manual of Bharat Prasad Sapkota at RyaleBhir, Panauti Municipality, Ward 1. This house was completed before Paus and has received second tranche.

Housing Typology Report



Address: Kavrepalanchok, Panauti 1, RyaleBhir
Building Typology: Stone in Mud with Wooden Band
Description: Parbati Sapkota constructed one roomed house beside her still inhabited pre earthquake house. In the slopy area as there was no sufficient land, one roomed structure of 15'X22' was constructed. This house has received second tranche.



Address: Kavrepalanchok, Panauti 1, RyaleBhir
Building Typology: Stone in Mud with Wooden Band
Description: Purna Kumari Sapkota, a single women constructed two roomed structure immediately after the earthquake to house her paralyzed mother in law. Following the non-compliances, DLPIU engineers suggested correction measures, following which the second tranche has been applied.



Address: Kavrepalanchok, Panauti 1, RyaleBhir
Building Typology: Stone in Mud with RCC Band
Description: Suresh Lama still inhabits the pre earthquake house and has constructed one roomed structure using the government subsidy. This house has been inspected for the second tranche.



Address: Kavrepalanchok, Panauti 1, RyaleBhir
Building Typology: Stone in Mud with Wooden Band
Description: Buddha Krishna Sapkota has completed constructing two roomed house but is using the house as shed and been living in pre earthquake house. This house has received second tranche and been inspected for the third tranche.



Address: Kavrepalanchok, Panauti 1, RyaleBhir
Building Typology: Stone in Mud with Wooden Band
Description: Krishna Prasad Sapkota used all salvaged materials for constructing his two roomed house costing him only the government subsidy. He listened to the BBS messages from radio and used those in construction and thinks trained masons are the most influential actors for building back safer. This house has received third tranche.



Address: Kavrepalanchok, Panauti 1, RyaleBhir
Building Typology: Stone in Mud with RCC Band
Description: The one roomed structure of Arjun Phuyal measures 19'X14'. He has been living in the pre earthquake house and constructed one room structure believing it is eligible for the tranches. This house has received second tranche.



Address: Kavrepalanchok, Panauti 1, RyaleBhir
Building Typology: Stone in Mud with RCC Band
Description: Bed Prasad Sapkota has constructed two roomed structure with regular consultations from DLPIU engineers. This house has received second tranche and been inspected for the third.



Address: Kavrepalanchok, Panauti 1, RyaleBhir
Building Typology: Stone in Mud with Wooden Band
Description: The deadline for housing reconstruction forced Bishnu Prasad Sapkota to construct one roomed house. As he is in his mourning year, he cannot demolish his damaged house. So, he was compelled to excavate the slopes and prepare land which was sufficient for constructing only one room structure.



Address: Kavrepalanchok, Panauti 1, RyaleBhir
Building Typology: Stone in Mud with RCC Band
Description: The one roomed house of Bharat Prasad Sapkota measures 15'X22'. This house has received second tranche.



Address: Kavrepalanchok, Panauti 1, RyaleBhir
Building Typology: Stone in Mud with RCC Band
Description: This one roomed structure of single woman Chandra Kumari Sapkota measures 15'X20'. This house has been inspected for second tranche.

Case Study

Niru Tamang of Thade, Kushadevi, Panauti Municipality, Ward 2 applied for Resurvey and Reverification but has heard that she did not make to the beneficiaries list. She had started living in her new house just some months before the earthquake. The constructions at that time in the area used no beams and bands, the absence of which was clearly seen in the results after the earthquake waves.

As the family did not make to the first beneficiary list, they sought guidance to retrofit the house but with no clarity of retrofitting techniques the family themselves moved on with filling cracks and installing steel posts to support the floor slab. Later they added a light framed storey and are living in the house. They do not have any clear idea if the retrofit process is correct and the house is safer.

