


FACTS AND FIGURES



Damage Status - Private Structures

Damage Grade (1-2)
122

Damage Grade (3-5)
8,447

MAJOR HOUSING TYPOLOGIES

Typology	Municipal	District
Stone and Mud Mortar Masonry	86.88%	90.24%
Adobe Structures	10.65%	2.85%
Reinforced Cement Concrete (RCC) Frame	0.83%	1.57%
Brick and Cement Mortar Masonry	0.79%	2.55%
Others	0.85%	2.79%

CBS damage assessment survey, 2015

HOUSING RECONSTRUCTION & RETROFIT UPDATES

Reconstruction Status

Total Eligible HHs	8,323
PA Agreement	8,052
I st Tranche received	8,052
II nd Tranche received	7,705
III rd Tranche received	6,163

Houses

Under Construction: -

Completed: -

Retrofitting Status

Total Eligible HHs	39
PA Agreement	11
I st Tranche received	7
II nd Tranche received	39

Grievances

Registered: 2,421

Addressed: 660

Non-compliances

Registered: -

Addressed: -

Data Updated on: 2019-05-27 00:00:00

P0 Presence

Active: PIN (Shelter)

Phased Out: GON-PAF (Shelter), JICA (Shelter), NNDSWO (Education), NRCS (Agriculture), NRCS (Education), NRCS (Livelihood), NRCS (Health), NRCS (Shelter), NRCS (Hygiene), NYF (Education), OXFAM-GB (Shelter), PIN (Governance), PIN (Shelter), PLAN (Education), PLAN (GESI), PLAN (Shelter), PLAN (Hygiene), SABAL (Shelter), SCI (Nutrition), UNDP (Shelter), WOREC (Shelter)

OTHER SECTORS



Schools

Damaged: 95
Under Construction: 36
Construction Completed: 36



Health Posts

Damaged: -
Under Construction: -
Construction Completed: -

STATUS OF CONSTRUCTION MATERIALS

Materials	Unit	Req. Quantity*	Ava.	Cost (NRs.)**
Stone	m ³	180,192	N	9,174
Aggregate	m ³	179,297	N	9,174
Sand	m ³	19,182	N	11,997
Timber	cu. ft.	21,924	-	-
Cement (PPC)	Sack	-	N	950
Cement (OPC)	Sack	590,291	N	1,000
Rebars	kgs.	1,955,348	N	85
Tin	bundle	24,088	-	-
Bricks	pcs.	1,467,471	N	15

Types of Workers

1. Skilled mason
2. Labourer

Avg. daily wage (NRs.)

1,200 /-
1,000 /-

KEY CONTACTS

Municipal Office

Bangsa Lal Tamang
Chairman
9860674432

Municipal Office

Manoj Dangal
Focal Person
9849261653

Municipal Office

Mira Adhikari Lama
Deputy Chairman
9808070820

GMaLI/NRA

NRA Chief-District

Municipal Office

Binod Rokka
Chief Administration Officer
9851210013

DLPIU-Building

Santosh Kumar Niraula
DUDBC.DLPIU Chief
9851136372

HHs WITH LAND ISSUES



STATUS OF TECHNICAL STAFF

Staff	Available Nos.	Additional Req. Nos.
Engineers	11	5
Sub-Engineers	12	10
Asst. Sub-Engineers	-	-
Masons	1,300 (7 days) - (50 days)	1,100 (7 days) - (50 days)

Source: Municipal survey

MASON TRAINING


Trainings (# out of total required)

7 days Training



Reached


50 days Vocational Training



Remaining

Source: HRRP Analysis

TA ACTIVITIES MAP



FAQs

Q: What documents are required for enrolment in the GoN housing reconstruction programme?

A: Two copies of passport size photos and original copy and photocopy of land ownership card and citizenship card. Local officials at the Rural / Urban Municipality will be able to provide information and support and households can enrol at the Rural / Urban Municipality.

Q: Do we need to pay the engineers when they come to conduct inspections or provide technical assistance?

A: No, you do not have to pay the engineers, or any other staff, conducting inspections or providing technical assistance. If any field staff request payment for conducting inspection or providing technical assistance you should report it to the Rural / Urban Municipality officials.

For further information 1. (District Coordinator) 2. Pradip Sharma (District Technical Officer) 3. (District Information Management Officer)
9851073208