


FACTS AND FIGURES



Damage Grade (1-2)
1,140

Damage Grade (3-5)
9,810

Damage Status - Private Structures

MAJOR HOUSING TYPOLOGIES

Typology	Municipal	District
Adobe Structures	45.83%	34.86%
Stone and Mud Mortar Masonry	24.76%	39.28%
Brick and Mud Mortar Masonry	20.05%	18.14%
Brick and Cement Mortar Masonry	4.91%	4.51%
Others	4.43%	3.22%

CBS damage assessment survey, 2015

HOUSING RECONSTRUCTION & RETROFIT UPDATES

Reconstruction Status

Total Eligible HHs	9,598
PA Agreement	7,938
I st Tranche received	7,870
II nd Tranche received	2,587
III rd Tranche received	2,122

Houses

Under Construction: -

Completed: -

Retrofitting Status

Total Eligible HHs	323
PA Agreement	89
I st Tranche received	87
II nd Tranche received	323

Grievances

Registered: 2,405

Addressed: 1,777

Non-compliances

Registered: -

Addressed: -

Data Updated on: 2019-05-16 00:00:00

P0 Presence

Active: No POs Reported

Phased Out: AA (DRM), AA (Education), AA (Livelihood), AA (GESI), BATAS (Shelter), EWDE-DKH (DRM), EWDE-DKH (Shelter), EWDE-DKH (Urban Housings), EWDE-DKH (Hygiene), LUMANTI (Shelter), LUMANTI (Hygiene), MCC (Agriculture), NRCS (Agriculture), NRCS (Education), NRCS (Livelihood), NRCS (Health), NRCS (Shelter), NRCS (Hygiene), NYF (Education), OXFAM-GB (Shelter), SDA (Shelter), SHANGRILA ORP (Shelter)

OTHER SECTORS



Schools

Damaged: 33
Under Construction: 21
Construction Completed: 21



Health Posts

Damaged: -
Under Construction: -
Construction Completed: -

STATUS OF CONSTRUCTION MATERIALS

Materials	Unit	Req. Quantity*	Ava.	Cost (NRs.)**
Stone	m ³	84,240	-	-
Aggregate	m ³	78,160	-	-
Sand	m ³	8,920	-	-
Timber	cu. ft.	10,018	-	-
Cement (PPC)	Sack	-	-	-
Cement (OPC)	Sack	261,810	-	-
Rebars	kgs.	927,581	-	-
Tin	bundle	10,696	-	-
Bricks	pcs.	1,665,441	-	-

Types of Workers

1. Skilled mason
2. Labourer

Avg. daily wage (NRs.)

-/-
-/-

KEY CONTACTS

Municipal Office

Gajendra Maharjan
Mayor
9851260016

Municipal Office

Bimala Dangol
Focal Person
9841508890

Municipal Office

Muna Adhikari
Deputy Mayor
9851235400

GMaLI/NRA

Bir Bahadur Rawal
NRA Chief-District
9851201088

Municipal Office

Krishna Prasad Jaisi
Administration Officer
9851250016

DLPIU-Building

Chandra Kaji Gurung
DUDBC.DLPIU Chief
9841576783

HHs WITH LAND ISSUES

No Reported Land Issues

STATUS OF TECHNICAL STAFF


Staff	Available Nos.	Additional Req. Nos.
Engineers	6	-
Sub-Engineers	6	-
Asst. Sub-Engineers	2	1
Masons	- (7 days) - (50 days)	- (7 days) 331 (50 days)

Source: Municipal survey

MASON TRAINING


Trainings (# out of total required)

7 days Training



Reached


50 days Vocational Training



Remaining

Source: HRRP Analysis

TA ACTIVITIES MAP



FAQs

Q: What documents are required for enrolment in the GoN housing reconstruction programme?

A: Two copies of passport size photos and original copy and photocopy of land ownership card and citizenship card. Local officials at the Rural / Urban Municipality will be able to provide information and support and households can enrol at the Rural / Urban Municipality.

Q: Do we need to pay the engineers when they come to conduct inspections or provide technical assistance?

A: No, you do not have to pay the engineers, or any other staff, conducting inspections or providing technical assistance. If any field staff request payment for conducting inspection or providing technical assistance you should report it to the Rural / Urban Municipality officials.

For further information

1. Ambika Amatya (District Coordinator)	2. (District Technical Officer)	3. Sachin Malego (District Information Management Officer)
9841356409	9861796464	9849166793