

District Report

Kavrepalanchok

5 – 19 July 2018

Summary of events during this period

Name of activity/event	Event date	Participants summary		Contact Person	Reference Document
		Male	Female		
GMALI/HRRP Coordination Meeting	9 July	11	3	reshma@hrrpnepal.org	Meeting Minutes
Vulnerability List Verification	Ongoing	-	-	reshma@hrrpnepal.org	File shared to DMT
Coordination and Capacity Strengthening at Urban and Rural Municipal Level	9 – 13 July	-	-	reshma@hrrpnepal.org	File shared to DMT
Case study support to the national daily on the impact of deadlines on reconstruction	8 July	-	-	im.kavrepalanchok@hrrpnepal.org	Not Applicable
Urban Reconstruction Scenario/Challenges	5 July	-	-	reshma@hrrpnepal.org	File shared to DMT
Orientation on NRA 5W Reporting	19 July			im.kavrepalanchok@hrrpnepal.org	Draft Discussions

Upcoming Events & Meetings

Name of activity/event	Date, Time, and Location	Organizer	Contact Person
Field Visit to RyaleBhir and Khopasi	23 July	HRRP Kavre	reshma@hrrpnepal.org
Field visit with NRA DSE to monitor non-compliance issues	26-27 July	HRRP Kavre	reshma@hrrpnepal.org

To include details of upcoming events and meetings in the next bulletin, please share details with reshma@hrrpnepal.org by COB Wednesday of each week.

News & Updates

- The Resurvey and Reverification List of all the 13 local structures have been received and forwarded to the respective Gaupalikas/Nagarपालikas along with the necessary documents and specifications for the future workings.

Housing Typology Report



Address: Kavrepalanchok, Panauti 12, KolatiBhumidanda

Building Typology: Stone in Mud with RCC Band

Description: Kanchi Bishwokarma has applied for the third tranche inspection. She received the second tranche from another house which collapsed due to heavy rainfall during construction.



Address: Kavrepalanchok, Panauti 11, Balthali

Building Typology: RCC

Description: Ram Hari Sharma is constructing the house using one untrained but skilled mason working for more than 15 years and all the rest new masons. As the new masons still are to learn the construction skills, some corrections were suggested in the ready to be cast pillars.



Address: Kavrepalanchok, Panauti 11, Balthali

Building Typology: Brick in Cement Masonry

Description: Sabin Lama constructed late as his land was insufficient after the newly laid road bylaws and setback. Due to the nearing deadline, he was compelled to go beyond and excavate the sloped land.



Address: Kavrepalanchok, Panauti 11, Balthali

Building Typology: Brick in Cement Masonry

Description: Bharat Bharati is constructing the superstructure contracting two skilled masons at NPR 1200 daily and two unskilled labour at NPR 600 daily. He had constructed till he plinth level a year before. After a year realizing that the planned two roomed structure is insufficient, without consultation with the engineers, relying on the masons, he is constructing a non-compliant four roomed house.



Address: Kavrepalanchok, Banepa 13, Sanga

Building Typology: Brick in Cement Masonry

Description: Saili Kami constructed her house with continuous technical assistance from the DLPIU engineers and has received the third tranche.



Address: Kavrepalanchok, Banepa 13, Sanga

Building Typology: Brick in Cement Masonry

Description: This structure of Krishna Bahadur Tamang is worth NPR 7.5 lakhs. He relied on the nearby Banepa market for the construction materials. He shared that the regular consultation with the technical persons resulted in the construction of a compliant house. But as the two roomed structure had no sufficient space for the kitchen, he had to construct a lean to kitchen.



Address: Kavrepalanchok, Banepa 11, Janagal

Building Typology: RCC

Description: Hari Sharan Tamang has received the third tranche after the non-compliance checked through the structural analysis by DSE.



Address: Kavrepalanchok, Banepa 11, Janagal

Building Typology: Brick in Cement Masonry

Description: Bed Prasad Ghimire constructed this house using NPR 23 lakhs. The high transportation cost resulted in the high sum.

Questions Collected

Question	Who Asked the Question?	Response Provided (By Whom)
What does the probable and potential beneficiary in the Resurvey and Reverification Addressal List mean?	Beneficiary	The Resurvey and Reverification List has classified the results as probable and potential beneficiaries on legal, technical or both merits for both reconstruction and retrofit beneficiaries. The probable beneficiaries would need to submit legal or technical documents to the ward for verification before being listed as the beneficiary. The potential beneficiaries who are the ones under multi-ownership will need to submit the family separation document verified before the earthquake.

Case Study

The traditional settlement of Panauti Municipality which at current constitutes Ward 7 of the municipality comprises more than 500 houses. This settlement has applied to be enlisted as World Heritage Site but as 78 houses are non-compliant to the heritage standards, the process is still in limbo.

Amongst the 438 reconstruction beneficiaries, 426 have been enrolled whereas 17 and 3 have received second and third tranche respectively. Furthermore, 12 additional houses have been inspected for the second tranche and 9 for the third tranche. So, considering both the received and inspected houses, 6.8% have applied for second tranche while 2.8% have applied for the third tranche. As per the ward official, Punya Lal Duwal, most of the families are staying in the pre earthquake house after minor repairs.

The strict heritage bylaw is the major reason for the lower reconstruction rate in the ward. According to the heritage area bylaws, the constructions must reflect the traditional architecture; brick façade and tile slopes. For the reconstruction, some leverage like construction permits in the previous foundation are allowed. Also since the inception of the municipality, there is a provision of supporting NPR 75,000 to construct traditionally in the core area but negligible people have applied for the tranche.

The next reason would be the approval for demolition of house. For every demolition, lengthy approval process from municipality needs to be undertaken. After the municipal approval and neighbor consent, regular presence of Army/Police too is required throughout the demolition process. Transportation/Clearance of debris and transportation of construction materials for reconstruction too is difficult in the traditional alleyways.

