


### FACTS AND FIGURES



Damage Status - Private Structures

### MAJOR HOUSING TYPOLOGIES

| Typology                               | Municipal | District |
|----------------------------------------|-----------|----------|
| Stone and Mud Mortar Masonry           | 88.64%    | 90.24%   |
| Adobe Structures                       | 7.83%     | 2.85%    |
| Reinforced Cement Concrete (RCC) Frame | 1.26%     | 1.57%    |
| Stone and Cement Mortar Masonry        | 1.06%     | 1.23%    |
| Others                                 | 1.21%     | 4.11%    |

CBS damage assessment survey, 2015

### HOUSING RECONSTRUCTION & RETROFIT UPDATES

#### Reconstruction Status

|                                    |       |
|------------------------------------|-------|
| Total Eligible HHs                 | 5,421 |
| PA Agreement                       | 5,205 |
| I <sup>st</sup> Tranche received   | 5,205 |
| II <sup>nd</sup> Tranche received  | 4,784 |
| III <sup>rd</sup> Tranche received | 3,817 |

#### Houses

Under Construction: -

Completed: -

#### Retrofitting Status

|                                   |    |
|-----------------------------------|----|
| Total Eligible HHs                | 52 |
| PA Agreement                      | 12 |
| I <sup>st</sup> Tranche received  | 6  |
| II <sup>nd</sup> Tranche received | 52 |

#### Grievances

Registered: 1,333

Addressed: 379

#### Non-compliances

Registered: -

Addressed: -

Data Updated on: 2019-05-27 00:00:00

### P0 Presence

Active: PIN (Shelter)

**Phased Out:** AA (DRM), AA (Education), AA (Livelihood), AA (GESI), AATWIN (Social Protection), CARITAS-S (DRM), CARITAS-S (Education), CARITAS-S (Hygiene), FAIRMED (Livelihood), FAIRMED (Health), FAIRMED (Hygiene), GHN (Education), HELVETAS (Agriculture), HELVETAS (Shelter), HELVETAS (Hygiene), NJSI (Shelter), NRCS (Health), NT (Education), NYF (Education), OXFAM-GB (Shelter), PIN (DRM), PIN (Governance), PIN (Shelter), PLAN (GESI), PLAN (Social Protection), SABAL (Shelter), SCI (Nutrition)

### OTHER SECTORS



#### Schools

Damaged: 51  
Under Construction: 34  
Construction Completed: 34



#### Health Posts

Damaged: -  
Under Construction: -  
Construction Completed: -

### STATUS OF CONSTRUCTION MATERIALS

| Materials    | Unit           | Req. Quantity* | Ava. | Cost (NRs.)** |
|--------------|----------------|----------------|------|---------------|
| Stone        | m <sup>3</sup> | 97,655         | Y    | -             |
| Aggregate    | m <sup>3</sup> | 92,157         | Y    | -             |
| Sand         | m <sup>3</sup> | 10,352         | Y    | 7,000         |
| Timber       | cu. ft.        | 11,672         | -    | -             |
| Cement (PPC) | Sack           | -              | Y    | 930           |
| Cement (OPC) | Sack           | 306,597        | Y    | 1,000         |
| Rebars       | kgs.           | 1,070,578      | Y    | 108           |
| Tin          | bundle         | 12,518         | -    | -             |
| Bricks       | pcs.           | 1,543,334      | Y    | 22            |

#### Types of Workers

1. Skilled mason
2. Labourer

#### Avg. daily wage (NRs.)

1,200 /-  
700 /-

### KEY CONTACTS

#### Municipal Office

Nima Gyaljen Sherpa  
Chairman  
9851048846

#### Municipal Office

Narayan Adhikari  
Focal Person  
9861147660

#### Municipal Office

Kopila Pandit  
Deputy Chairman  
9860281422

#### GMaLI/NRA

NRA Chief-District

#### Municipal Office

Bhim Raj Koirala  
Chief Administration Officer  
9801017857

#### DLPIU-Building

Santosh Kumar Niraula  
DUDBC.DLPIU Chief  
9851136372

## HHs WITH LAND ISSUES

No Reported Land Issues


## STATUS OF TECHNICAL STAFF

| Staff               | Available Nos.            | Additional Req. Nos.      |
|---------------------|---------------------------|---------------------------|
| Engineers           | 7                         | 3                         |
| Sub-Engineers       | 4                         | 5                         |
| Asst. Sub-Engineers | 5                         | 2                         |
| Masons              | - (7 days)<br>- (50 days) | - (7 days)<br>- (50 days) |

Source: Municipal survey


## MASON TRAINING

Trainings (# out of total required)



Source: HRRP Analysis

## TA ACTIVITIES MAP



## FAQs

**Q: What documents are required for enrolment in the GoN housing reconstruction programme?**

A: Two copies of passport size photos and original copy and photocopy of land ownership card and citizenship card. Local officials at the Rural / Urban Municipality will be able to provide information and support and households can enrol at the Rural / Urban Municipality.

**Q: Do we need to pay the engineers when they come to conduct inspections or provide technical assistance?**

A: No, you do not have to pay the engineers, or any other staff, conducting inspections or providing technical assistance. If any field staff request payment for conducting inspection or providing technical assistance you should report it to the Rural / Urban Municipality officials.

**For further information** 1. (District Coordinator) 2. Pradip Sharma (District Technical Officer) 3. (District Information Management Officer)  
9851073208

@HRRP

/photos/hrrp

@HRRP\_Nepal

HRRPNepal

www.hrrpnepal.org

CONNECT WITH US