

District Report

Dhading

23 February – 1 March 2018

Activity Summary

Activity	Contact Person	Reference Document
HRRP district coordination meeting was held on 26th Feb 2018. Following were the main agendas of the meeting: • HRRP Reconstruction Survey • Findings of the field visit • DLPIU, NRA and HRRP Housing Reconstruction Updates • District Exhibition on Reconstruction • AOB	techcord.dhading@hrrpnepal.org dc.dhading@hrrpnepal.org	Meeting Minute can be accessed Here.
HRRP survey on reconstruction. Following are the major of the topics: • Temporary Shelter • Women in Reconstruction • Community Reconstruction Committee Field survey at Ward no.: 2 and Ward no.: 1 of Tripurasundari Rural Municipality from (26th Feb– 1st March) 2018.	dc.dhading@hrrpnepal.org techcord.dhading@hrrpnepal.org	Mobile forms were collected during the field survey and submitted to National HRRP.
HRRP supported MoFALD /DLPIU for PA collection at Phulkharka, Gumdi, Goganpani & Katunje VDCs. – MIS specialist of EHRP has kept record of it.	dc.dhading@hrrpnepal.org	

Upcoming Events & Meetings

Event / Meeting	Date, Time, and Location	Contact Person
“CSEB workshops” for NRA engineers at district.	Planned on March 2018	Build Up Nepal
HRRP survey on reconstruction.	5 th to 8 th March, 2018.	dc.dhading@hrrpnepal.org techcord.dhading@hrrpnepal.org
To include details of upcoming events and meetings in the next bulletin, please share details with dc.dhading@hrrpnepal.org by COB Wednesday of each week.		

Field Visit Reports

Date:	Location	Participants
Feb (26 th Feb – 1 st March), 2018	Tripurasundari Ga. Pa, Ward no.: 2 and Ward no.: 1	• Prabin Gautam (HRRP) - DC • Sachin Sapkota (HRRP) - DTC
Objective(s)	HRRP survey on reconstruction. Following are the major of the topics: • Temporary Shelter • Women in Reconstruction • Community Reconstruction Committee   A camp was established at Pauwadil village of Ward no.: 2, Tripurasundari RM. People were still living at temporary shelter. These people have been migrated from Lapa VDC of Ruby Valley RM. Most the houses were critically damaged by the earthquake and they were at a high risk of landslide at the place of origin. Thus, they had to migrate to a safer place for living. Staying at Pauwadil village, they feel safer and children have good access to school, health and sanitation.	

Housing Typology Report



Address: - Gumdi-04, Gangajamuna Rural Municipality.
Type of house:- Stone masonry in mud mortar with RCC Bands
Received 1st Tranche, Approved for 2nd Tranche



Address: - Gumdi-04, Gangajamuna Rural Municipality.
Type of house:- One story load bearing structure, stone masonry in mud mortar with RCC band
Received 2nd Tranche, Approved for 3rd Tranche



Address: - Gumdi-04, Gangajamuna Rural Municipality.
Type of house:- One story load bearing structure, stone masonry in mud mortar with wooden band
Received 1st Tranche, Approved for 2nd Tranche



Address: - Semjong, Netrawati Rural Municipality.
Type of house:- RCC framed structure building with brick masonry in C/M .