


FACTS AND FIGURES



Damage Status - Private Structures

MAJOR HOUSING TYPOLOGIES

Typology	Municipal	District
Stone and Mud Mortar Masonry	89.41%	90.24%
Dry Stone Masonry	6.72%	1.08%
Stone and Cement Mortar Masonry	1.39%	1.23%
Reinforced Cement Concrete (RCC) Frame	1.39%	1.57%
Others	1.08%	5.88%

CBS damage assessment survey, 2015

HOUSING RECONSTRUCTION & RETROFIT UPDATES

Reconstruction Status

Total Eligible HHs	7,181
PA Agreement	6,794
I st Tranche received	6,794
II nd Tranche received	6,326
III rd Tranche received	3,628

Houses

Under Construction: -

Completed: -

Retrofitting Status

Total Eligible HHs	20
PA Agreement	3
I st Tranche received	3
II nd Tranche received	20

Grievances

Registered: 2,937

Addressed: 1,424

Non-compliances

Registered: -

Addressed: -

Data Updated on: 2019-05-27 00:00:00

P0 Presence

Active: CARE-N (Hygiene), DH (Shelter), PIN (Shelter), TGH (Shelter)

Phased Out: AATWIN (Social Protection), ARSOW-TGH (Shelter), CARE-N (Agriculture), CARE-N (DRM), CARE-N (GESI), CARE-N (Shelter), CARE-N (Hygiene), CMI-N (Education), DSCBD (Education), FAIRMED (Livelihood), FAIRMED (Health), FAIRMED (Hygiene), GHN (Education), GON-PAF (Shelter), NRCS (Agriculture), NRCS (Education), NRCS (Livelihood), NRCS (Health), NRCS (Shelter), NRCS (Hygiene), PIN (Agriculture), PIN (DRM), PIN (Governance), PIN (Shelter), PLAN (GESI), PLAN (Shelter), PLAN (Social Protection), PLAN (Hygiene), SABAL (Shelter), SCI (Nutrition), TGH (Agriculture), TGH (DRM), TGH (Livelihood), TGH (Shelter), TGH (Transport), TGH (Hygiene)

OTHER SECTORS



Schools

Damaged: 54
Under Construction: 28
Construction Completed: 28



Health Posts

Damaged: -
Under Construction: -
Construction Completed: -

STATUS OF CONSTRUCTION MATERIALS

Materials	Unit	Req. Quantity*	Ava.	Cost (NRs.)**
Stone	m ³	121,331	Y	-
Aggregate	m ³	111,904	Y	-
Sand	m ³	12,835	Y	-
Timber	cu. ft.	14,374	Y	-
Cement (PPC)	Sack	-	Y	-
Cement (OPC)	Sack	370,950	Y	-
Rebars	kgs.	1,331,616	Y	-
Tin	bundle	15,130	Y	-
Bricks	pcs.	1,831,727	Y	-

Types of Workers

1. Skilled mason
2. Labourer

Avg. daily wage (NRs.)

1,500 /-
1,000 /-

KEY CONTACTS

Municipal Office

Tashi Lama Hyolmo
Chairman
9803275836

Municipal Office

Benjamin Shrestha
Focal Person
9843200490

Municipal Office

Sunita Adhikari
Deputy Chairman
9803805437

GMaLI/NRA

NRA Chief-District

Municipal Office

Sanjay Kumar Singh
Chief Administration Officer
9805928539

DLPIU-Building

Santosh Kumar Niraula
DUDBC.DLPIU Chief
9851136372

HHs WITH LAND ISSUES

No Reported Land Issues

STATUS OF TECHNICAL STAFF

Staff	Available Nos.	Additional Req. Nos.
Engineers	8	0
Sub-Engineers	5	3
Asst. Sub-Engineers	5	3
Masons	1,020 (7 days) 125 (50 days)	0 (7 days) 0 (50 days)

Source: Municipal survey

MASON TRAINING


Trainings (# out of total required)

7 days Training



Reached


50 days Vocational Training



Remaining

Source: HRRP Analysis

TA ACTIVITIES MAP



FAQs

Q: What documents are required for enrolment in the GoN housing reconstruction programme?

A: Two copies of passport size photos and original copy and photocopy of land ownership card and citizenship card. Local officials at the Rural / Urban Municipality will be able to provide information and support and households can enrol at the Rural / Urban Municipality.

Q: Do we need to pay the engineers when they come to conduct inspections or provide technical assistance?

A: No, you do not have to pay the engineers, or any other staff, conducting inspections or providing technical assistance. If any field staff request payment for conducting inspection or providing technical assistance you should report it to the Rural / Urban Municipality officials.

For further information 1. (District Coordinator) 2. Pradip Sharma (District Technical Officer) 3. (District Information Management Officer)
9851073208