

District Report

Kavrepalanchok

28 September-5 October 2017

Activity Summary

Activity	Contact Person	Reference Document
Meeting Calendar Update	Reshma Shrestha	HRRP Website
HRRP Coordination Meeting Planning	Reshma Shrestha	

Upcoming Events & Meetings

Event / Meeting	Date, Time, and Location	Contact Person
HRRP Coordination Meeting	10/09/2017, 11:30 AM, Dhulikhel	Reshma Shrestha

Field Visit Reports

Date	Location	Participants
6th October 2017	Ojhetar, Panchkhal Municipality	- HRRP Technical Officer, Kuber Bogati - HRRP Kavre, Reshma Shrestha

Objective(s)

- For detailed study and measurements of Adobe constructions in Ojhetar, Panchkhal Municipality.

Summary

During the Field Visit conducted by HRRP Kavre to Ojhetar on 7th September 2017, preliminary information was collected on the completed and ongoing Adobe constructions. As the adobe structures are covered by the National Building Code of Nepal but not considered for the reconstruction program, more details were required. So, the houses visited during the earlier visits were measured and studied in detail. One of the construction with RCC band was found to be in compliance to the national building code. Through general observation, most all of the constructions in adobe with wooden band missed one or more components, but conclusions can be drawn after the detail analysis of the information collected.

Photos



District Report

Housing Recovery and Reconstruction Platform, Nepal



Housing Recovery and
Reconstruction Platform

This house sees all the earthquake resistant elements but the construction is on adobe. The house owner Pushpa Maya Danuwar has received the municipal permit for this design as well. (Ojheta, Panchkhal Municipality)	
--	--