

District Report

Sindhupalchok

23 Feb – 1 March 2018

Activity Summary

Activity	Contact Person	Reference Document
Conducted survey in the field: Total 51 survey forms completed during the 2 days (27-28 Feb) field survey in 4 VDCs. It indicates 50% survey of field survey has been completed to the date.	Techcord.sindhupalchok@hrrpnepal.org Im.sindhupalchok@hrrpnepal.org	
Info Pack distribution: As per the last week plan, district team distributed and visited GoN offices, CDO, LDO, NRA along with national team before to move to field for survey on 26-Feb. We informed them regarding to survey and discussed on other issues related reconstruction.	Im.sindhupalchok@hrrpnepal.org Techcord.sindhupalchok@hrrpnepal.org	
4W and mason training database update	Im.sindhupalchok@hrrpnepal.org	
Participated on program organized by JICA	Techcord.sindhupalchok@hrrpnepal.org	

Upcoming Events & Meetings

Event / Meeting	Date, Time, and Location	Contact Person
Palika level meeting in Melamchi N.P.	TBC	Techcord.sindhupalchok@hrrpnepal.org

Field Visit Reports

Date		Location	Participants
27-28 Feb-18		Syaule, Sangachok, Irkhu and Chautara N.P.	Sufi Mohammad, Manisha Rai, Dipak Saud and Aarju Basnet
Objective	To conduct survey on temporary shelter, woman beneficiary, woman mason and CRC.		
Summary	As plan and scheduled by HRRP, we prepared a plan to start the survey from 27 th Feb in Sindhupalchok district. We divided in two groups among us as 2 from national team were with us to support in the district. In coordination with POs and DLPIU engineers, SM we completed it more than 50% of field survey. We found many beneficiaries are living in temporary shelters whose house is under construction. Few of those were single women and have not started reconstruction yet. For example, out of 7 temporary shelters, 3 were of single women and elderly as well in a VDC (Syaule).		
Pictures			



A Single elderly woman is helpless on reconstruct her house. Her previous house was completely damaged and now living in a temporary CGIs shelter in the side of her younger sisters' temporary shelter in Syaule VDC/Chautara Sangachokgadhi N.P. ward no 1. She is living alone since her husband died and daughters got married, she has not son.



During an interview/survey of woman beneficiary and temporary shelter in front of her T shelter. She lives in the side of her younger sisters' T shelters. Both sisters are single woman beneficiaries. Both have not started reconstruction though they had received I tranche in the beginning.



A woman mason trained by UN-Woman/Saathi is working as labor in reconstruction in own village, Irkhu VDC/Chautara Sangachok Gadhi N.P. ward no. 8



Three brothers new houses in a same tarrace in Irkhu VDC/ChautaraSangachokGadhi N.P. ward no 8. All have received II tranche and completed inspection for III tranche.