

District Report

Kathmandu Valley

16-22 March 2018

Activity Summary

Activity	Contact Person	Reference Document
General coordination meeting of Kathmandu district with NRA, DLPIU-MOUD, CLPIU-MOFALD, POs and HRRP was conducted on 18 March 2018 at NRA Lalitpur Office. The agendas of the meeting were as follows: → NRA decision to DLPIU and POs → Updates of each POs and from DLPIU The major decision made during the meeting were as follows: → NRA Lalitpur informed to keep the list of trained Masons by concerned POs at respective project ward office so that the masons can be contacted for reconstruction of individual houses. → NRA Lalitpur informed POs to take technical support from DLPIU MOE for design approval of infrastructures like toilet construction and set up of water tanks, rainwater harvesting etc. that is targeted to be placed in earthquake affected schools. → NRA Lalitpur informed POs about the directives from central NRA that mentions about the eligibility of 2nd tranche to those beneficiaries only who have reconstructed the houses by demolishing the previous house damaged by the earthquake. NRA Lalitpur requested POs to inform the beneficiaries in their respective project areas about this provision. → NRA requested HRRP Kathmandu Valley Team to coordinate with POs that has completed its project activities in Lalitpur district for the mandatory presence in next coordination meeting with the final project completion report.	Ambika Amatya dc.ktm@hrrpnepal.org	The minute of the meeting will be forwarded later.
Interaction meeting was organized regarding progress and challenges of faced in private housing reconstruction in Kathmandu Valley at NRA Central Office on 19 March 2018.	Mr. Prem Prasad Ghimire, NRA Chief, Kathmandu 9841637299	
3rd Event of Mason Training is under progress at Nallu area on 18-24 March 2018, supported by Nepal Red Cross Society (NRCS), Lalitpur	Hari Sapkota, hari.sapktoa@gmail.com NRCS Lalitpur 9841167703	
A joint field monitoring visit was conducted at Nagarjun Municipality, Kathmandu district by HRRP Kathmandu valley team and M & E Consultant, MOUD-CLPIU on 20 March 2018	Ambika Amatya dc.ktm@hrrpnepal.org	

Activity Summary

A joint field monitoring visit was conducted at Chandragiri Municipality, Kathmandu district by HRRP Kathmandu valley team and M & E Consultant, MOUD-CLPIU on 21 March 2018	Ambika Amatya dc.ktm@hrrpnepal.org	
Infopacks were distributed to Mayor as well as to Chief Executive Officer of Nagarjun Municipality on 20 March	Ambika Amatya dc.ktm@hrrpnepal.org	
Field Monitoring in various municipalities of Kathmandu district by NRA Kathmandu on different dates of March 2018 (Chaitra 2074)	Mr. Prem Prasad Ghimire, NRA Chief, Kathmandu 9841637299	

Upcoming Events & Meetings

Event / Meeting	Date, Time, and Location	Contact Person
Joint Field Monitoring by HRRP Kathmandu valley team and M & E Consultant CLPIU-MOUD	27-30 March 2018, various wards of Godawari Municipality, Lalitpur Metropolitan City and Konjyom Rural Municipality	Ambika Amatya dc.ktm@hrrpnepal.org
Joint Field Monitoring by HRRP Kathmandu valley team and M & E Consultant CLPIU-MOUD	2 April 2018, various wards of Tarkeshwor Municipality	Ambika Amatya dc.ktm@hrrpnepal.org
Field Monitoring in various parts municipalities in Kathmandu district by NRA Kathmandu	Various dates of March 2018 (Chaitra 2074)	Mr. Prem Prasad Ghimire, NRA Chief, Kathmandu 9841637299
Mason Training at Dakshinkali Municipality by NRA Kathmandu	Status: TBD soon in March-April 2018 (Chaitra 2074)	Mr. Prem Prasad Ghimire, NRA Chief, Kathmandu 9841637299
Review Meeting regarding Progress and Challenges of Reconstruction in Kathmandu district	13 April 2018 (30 Chaitra 2074), at DCC Kathmandu	Mr. Prem Prasad Ghimire, NRA Chief, Kathmandu 9841637299
To include details of upcoming events and meetings in the next bulletin, please share details with dc.ktm@hrrpnepal.org by COB Wednesday of each week.		

News & Updates

Reconstruction updates: Different areas of Lalitpur district

Areas of Lalitpur district	Total Beneficiaries	Total beneficiaries with PA agreement	Beneficiaries that received 1st tranche	Beneficiaries that has started reconstruction	Beneficiaries that has applied for 2nd tranche	Beneficiaries that has been verified for 2nd tranche	Beneficiaries that has applied for 3rd tranche	Beneficiaries that has been verified for 3rd tranche	Beneficiaries that has received construction completion
Ghusel	384	313	298	148	143	143	125	125	12
Devichaur	685	445	384	60	59	48	14	26	2
Bajrabarahi	4023	3098	2588	324	234	203	186	155	1
Gimdi	591	547	561	485	463	463	105	103	4
Thuladurlung	401	376	355	120	114	114	9	9	
Chaughare	426	402	399	50	50	50	16	16	1
Ashrang	251	167	167	55	77	77	35	35	3
Malta	541	415	406	134	123	123	50	50	5
Bhattedanda	570	541	535	265	260	257	150	141	14
Lalitpur Sub Metropolitan	5169	4418	4302	700	700	666	280	280	5
Kaleshwor	345	337	333	120	110	110	39	39	5
Bukhel	464	453	453	238	233	221	72	56	3
Pyutar	329	319	315	150	80	80	20	20	2
Bhardeu	201	191	161	65	52	46	24	21	2
KaryaBinayak	3305	2461	2095	20	10	5	10		1
Chandanpur	247	243	243	40	25	19	5	10	1
Dahachok	393	354	333	240	244	196	240	189	19
Nallu	434	414	407	395	386	377	100	97	9
Sangkhu	658	609	605	305	305	289	76	41	8
Ikudol	525	479	475	165	159	159	39	39	3
Gotikhel	340	337	337	90	88	85	32	30	3
MahaLakshmi	3520	2709	2653	499	474	383	395	300	15
Manikhel	426	426	419	250	244	244	26	26	2
Godawari	3246	2248	2012	280	270	185	208	139	11
Total	27474	22302	20836	5198	4903	4543	2256	1947	137

Field Visit Reports- Visit 1

Date	Location	Participants
20 March 2018	Nagarjun Municipality, Ward no. 3, Ichangu, Halchowk Kathmandu district	- Narakanta Sapkota, M & E Consultant, MOUD CLPIU - Ambika Amatya (District Coordinator- Kathmandu Valley) - Shristi Gautam, Engineer, Nagarjun Municipality - Pratima Yadav, Engineer, Nagarjun Municipality - Nina Riehle, International, Volunteer, HRRP
Objective(s)	- To observe the reconstruction status of the beneficiaries - To conduct surveys whereby using digitized forms for the surveys including. - To provide inputs to the beneficiaries in regards of housing reconstruction and for grant receipt process.	
Summary	HRRP Kathmandu valley team with a monitoring team from CLPIU MOUD conducted field visit at Ward No. 3 of Nagarjun Municipality. The purpose of conducting the visit comprises of monitoring the progress status of the houses in reconstruction phase as well as to provide inputs to the house owners. The monitoring team also met the elected representative along with staff involved in the reconstruction activities of Nagarjun Municipality.	

	As per the reconstruction update provided by the Mr. Mohan Bahadur Basnet, Mayor, Nagarjun Municipality: The identified earthquake affected households in Nagarjun Municipality is 3800, among which only 800 households have done PA agreement with the government. The interaction revealed that the reconstruction efforts in various parts of Nagarjun Municipality has been entangled by the land issues. The majority of the land issues is related with Guthi (trust) land, multiple beneficiaries, disputes between tenant farmers and land owners and poverty of the landless people. as well A total of 7 houses in reconstruction phase were observed by the monitoring team. The interaction concluded with a note that the cases of multiple beneficiaries and Guthi land of the beneficiaries can be solved through Sarjamin (public inquiry deed) in coordination with ward office and municipality. The earthquake affected households in Putuwar Tole, Ward no. 3, Ichangu, Halchowk area, Nagarjun Municipality has been enduring with cases of multiple beneficiaries and lack of land ownership papers. Majority of houses were severely damaged by Nepal earthquake which made them to reside in temporary shelters. While most of the affected Putuwar people have managed to reconstruct the house, many of the houses do not have approved building drawing and were found to be non compliance during the monitoring visit. As per the reconstruction update provided by Shukra Bahadur Tamang, Ward Chief – 8, Nagarjun Municipality: The joint monitoring team interacted with the Ward Chief -8. The reconstruction issues in Bhimdhunga, Ward no. 8, Nagarjun Municipality shared that the reconstruction issues in areas of Bhimdhunga is related with land ownerships cases between tenant farmers and land owners. Majority of earthquake affected beneficiaries have reconstructed their houses before the formal guidelines building codes issued by Government of Nepal. The pertinent issues in housing reconstruction at Bhimdhunga are the remoteness, lack of skilled masons, high cost of existing labours and lack of awareness among the earthquake affected people. The tranche updates of ward no. 8, Bhimdhunga is- ▪ 1st tranche- 605 hhs ▪ 2nd tranche- 23 hhs ▪ 3rd tranche 5 hhs		
Challenges / Issues Identified	Action Required	Responsible	Timeframe
Majority of earthquake affected households have reconstructed the houses without following the minimum requirements of national building code.	The concerned ward office and municipality need to conduct massive community sensitization program whereby issuing Public Information Notice on Chaitra end deadline for receiving 2 nd tranche and for mandatory building drawing of houses. Similarly, frequent monitoring visit should be conducted by engineers in order to inform people about formal guidelines of corrective measures for the houses that have already been reconstructed.	Beneficiaries, local bodies, NRA Kathmandu.	As soon as possible
Lack of land ownership papers is delaying the process of building drawing approval as well as further delays in claiming the further tranches is likely.	The Grievances Committee of concerned municipality and ward office should immediately interact with beneficiaries for solving this particular problem of land ownership papers.	Beneficiaries, land owners, local bodies, NRA Kathmandu.	As soon as possible

Photos



Ichangu, Halchowk, Ward No. 3, Nagarjun Municipality, RCC frame structure building. The house owner belongs to Putuwar community that stands on a firm rock structure at Ichangu, Halchowk. The house is in reconstruction phase without following the minimum requirement of national building code and the house owner does not possess building drawing map. The beneficiary has received 1st tranche.



Ichangu, Halchowk, Ward No. 3, Nagarjun Municipality, BMC structure building. The house owner belongs to Putuwar community that stands on a firm rock structure at Ichangu, Halchowk. The house owner has reconstructed the house immediately after the earthquake damaged their previous building and without following the building code. The house owner does not possess approved building drawing. The beneficiary has received 1st tranche.



Ichangu, Halchowk, Ward No. 3, Nagarjun Municipality, BMC structure building. The house owner belongs to Putuwar community that stands on a firm rock structure at Ichangu, Halchowk. The house owner has received the 2nd tranche.



Ramkot, Fakshu, Ward No. 2, Nagarjun Municipality, BMC, wall system building. The house owner has forwarded file for 2nd tranche whereas the building drawing is under process. The house is compliance according to the building guidelines.

Field Visit Reports- Visit 2

Date	Location	Participants
21 March 2018	Ward no. 1, Dahachowk Ward no. 1, Jhyangajhiti Chandragiri Municipality, Kathmandu district	• Narakanta Sapkota, M & E Consultant, MOUD CLPIU • Monika Bajimaya Shrestha, DMT IM Coordinator, HRRP • Ambika Amatya (District Coordinator- Kathmandu Valley, HRRP) • Cherina Awale, Engineer, Chandragiri Municipality

Objective(s)	- To observe the reconstruction status of the beneficiaries - To conduct surveys whereby using digitized forms for the surveys including. - To provide inputs to the beneficiaries in regards of housing reconstruction and for grant receipt process.		
Summary	HRRP Kathmandu valley team with a monitoring team from CLPIU MOUD conducted field visit at Ward No.1, Dahachowk and Jhyangajhiti areas of Chandragiri Municipality. The purpose of conducting the visit comprises of monitoring the progress status of the houses in reconstruction phase as well as to provide inputs to the house owners. The monitoring team interacted with the community members of Jhyagajhiti area regarding the reconstruction issues. A total of 116 households were severely affected by the Nepal earthquake, among which 30-35 households have been reconstructed sometime after residing at the temporary shelters. However still households have continued to live in temporary shelters. The major reconstruction issues of Jhyangajhiti area is the case of multiple beneficiaries, lack of land ownership papers, lack of building drawing and lack of public awareness about guideline and regulations of housing reconstruction. Though the area falls in the Municipality territory, lack of proper road connections has disrupted the monitoring from the government side including of Ward office and engineers from Municipality. Around 9 houses of Jhyangajhiti were monitored by the team which revealed that majority of the houses were reconstructed by the beneficiaries after residing in temporary shelters for certain time. Similarly, majority of the house owners do not have building drawing and also many of them were non-compliance as per the building code. Lack of land ownership paper is another major issue entangled with the beneficiaries of Jhyangajhiti that has received 1st tranche only. Many of the monitored house has stone masonry with mud mortar structure while roof is covered by the CGI sheets. Furthermore, half way up of the wall has been covered by the CGI sheets that makes the houses to fall under non-compliance category. M & E Consultant recommended the beneficiaries to follow up with the engineers of Chandragiri Municipality for proper information on retrofitting procedures as well as the technical support in order to receive the 2nd tranche in timely manner.		
Challenges / Issues Identified	Action Required	Responsible	Timeframe
Reconstructed houses of SMC structure were found against the minimum requirements of national building code.	The concerned Ward office and Municipality office should take affirmative measures to provide technical help desk in terms of sensitizing the communities about relevant retrofitting procedures so that the beneficiaries can receive the 2 nd tranche subsequently.	Beneficiaries, local bodies, NRA Kathmandu.	As soon as possible

Photos



Dahachowk, Ward no. 1, Chandragiri Municipality, BMC structure, 3-room house targeted for wall system with CGI sheets as roof. The house owner do not possess building drawing map. The beneficiary has received 1st tranche.



Dahachowk, Ward no. 1, Chandragiri Municipality, SMC structure at DPC level. The house owner do not possess approved building drawing. The beneficiary has received 1st tranche.



Jhyangajhiti, Ward no. 1, Chandragiri Municipality, SMC structure building with CGI roof. 1 room house having an area 140 sq km is found to have met the minimum requirements of national building code. The house owner were recommended to keep either RC band or replace the gable wall with CGI sheet in order to receive 2nd tranche.



Jhyangajhiti, Ward no. 1, Chandragiri Municipality, SMC structure building with CGI roof. The house were reconstructed without following minimum requirements of national building code and the owner do not possess building drawing. The owner were recommended to follow retrofitting procedures from the concerned municipality in order to receive 2nd tranche.



Jhyangajhiti, Ward no. 1, Chandragiri Municipality, SMM structure building with CGI roof. The house were reconstructed without following minimum requirements of national building code and the owner do not possess building drawing. The owner were recommended to follow retrofitting procedures from the concerned municipality to receive 2nd tranche.



Jhyangajhiti, Ward no. 1, Chandragiri Municipality, SMM structure building with CGI roof. The house were reconstructed without following national building code and the owner do not possess building drawing. The owner were recommended to follow retrofitting procedures from the concerned municipality to receive 2nd tranche.

Questions Collected

Question	Who Asked the Question?	Response Provided (By Whom)
In want of secure shelter, majority of house owners in Jhyangajhiti were forced to reconstruct our houses after living in temporary shelters for certain time but what can be done to receive 2 nd tranche ?	Beneficiary	As the house is already reconstructed by spending a good deal of money, retrofitting procedures can be applied that has been made with SMC and SMM structure. Majority of houses in Jhyangajhiti area is noncompliance and donot meet the minimum requirements of national building code. Hence, one member from this community can take lead in collectively representing the similar cases of the reconstructed houses and forward it to Chandragiri Municipality for the need of technical support in retrofitting measures. This initiation should be undertaken as soon as possible in light of approaching deadline of Chaitra end to claim 2 nd tranche. (M & E Consultant, CLPIU MOUD)

Challenges and Way Forward

Challenge	Way Forward
In want of proper shelter, earthquake beneficiaries that have reconstructed their houses which in fact do not meet the minimum requirements of national building code, have chances of missing the subsequent tranches in upcoming days if delays perpetuate.	The concerned municipality should take affirmative measures of deploying technical support team in such areas that has cases of non-compliances. There is rampant need of sensitization programs in such areas in order to provoke communities so that they can forward the reconstruction issues at municipality level in time.