


FACTS AND FIGURES



Damage Status - Private Structures

Damage Grade (1-2)
389

Damage Grade (3-5)
3,294

MAJOR HOUSING TYPOLOGIES

Typology	Municipal	District
Stone and Mud Mortar Masonry	63.00%	82.76%
Dry Stone Masonry	33.39%	4.17%
Timber Frame Structure	1.71%	0.88%
Brick and Cement Mortar Masonry	0.65%	2.57%
Others	1.26%	9.63%

CBS damage assessment survey, 2015

HOUSING RECONSTRUCTION & RETROFIT UPDATES

Reconstruction Status

Total Eligible HHs	4,169
PA Agreement	3,794
I st Tranche received	3,794
II nd Tranche received	3,259
III rd Tranche received	2,800

Houses

Under Construction: 459 Completed: 2,800

Retrofitting Status

Total Eligible HHs	280
PA Agreement	29
I st Tranche received	86
II nd Tranche received	0

Grievances

Registered: 1,121
Addressed: 394

Non-compliances

Registered: -
Addressed: -

Data Updated on: 2019-05-27 00:00:00

P0 Presence

Active: CARE-N (Agriculture), CARE-N (Livelihood), UNDP (Shelter)

Phased Out: CARE-N (Agriculture), CARE-N (DRM), CARE-N (GESI), CARE-N (Health), CARE-N (Shelter), CARE-N (Hygiene), CRS (Agriculture), CRS (Livelihood), CRS (Shelter), FCA (Education), GHA (Education), GON-PAF (Shelter), INF (Livelihood), MECS (Education), NRNA (Shelter), OXFAM-GB (Shelter), SCI (Shelter), UNDP (Shelter), WFP (Livelihood)

OTHER SECTORS



Schools

Damaged: 39
Under Construction: 16
Construction Completed: 16



Health Posts

Damaged: -
Under Construction: -
Construction Completed: -

STATUS OF CONSTRUCTION MATERIALS

Materials	Unit	Req. Quantity*	Ava.	Cost (NRs.)**
Stone	m ³	54,090	-	-
Aggregate	m ³	55,574	-	-
Sand	m ³	5,774	-	-
Timber	cu. ft.	6,658	-	-
Cement (PPC)	Sack	-	Y	2,200
Cement (OPC)	Sack	182,394	Y	2,400
Rebars	kgs.	583,888	N	-
Tin	bundle	7,444	-	-
Bricks	pcs.	262,940	N	-

Types of Workers

1. Skilled mason
2. Labourer

Avg. daily wage (NRs.)

1,500 /-
1,000 /-

KEY CONTACTS

Municipal Office

Santa Bahadur Gurung
Chairman
9551019353

Municipal Office

Baburam Pandey
Focal Person
9851164646

Municipal Office

Ful Maya Gurung
Deputy Chairman
9846722405

GMaLI/NRA

Ram Sharan Acharya
NRA Chief-District
9856042637

Municipal Office

Babu Ram Pandey
Chief Administration Officer
9851164646

DLPIU-Building

Sunita Shrestha
DUDBC.DLPIU Chief
9841632087

HHs WITH LAND ISSUES

No Reported Land Issues

STATUS OF TECHNICAL STAFF


Staff	Available Nos.	Additional Req. Nos.
Engineers	-	-
Sub-Engineers	-	-
Asst. Sub-Engineers	-	-
Masons	1,016 (7 days) 574 (50 days)	1,500 (7 days) 1,000 (50 days)

Source: Municipal survey

MASON TRAINING


Trainings (# out of total required)

7 days Training



Reached


50 days Vocational Training



Remaining

Source: HRRP Analysis

TA ACTIVITIES MAP



FAQs

Q: What documents are required for enrolment in the GoN housing reconstruction programme?

A: Two copies of passport size photos and original copy and photocopy of land ownership card and citizenship card. Local officials at the Rural / Urban Municipality will be able to provide information and support and households can enrol at the Rural / Urban Municipality.

Q: Do we need to pay the engineers when they come to conduct inspections or provide technical assistance?

A: No, you do not have to pay the engineers, or any other staff, conducting inspections or providing technical assistance. If any field staff request payment for conducting inspection or providing technical assistance you should report it to the Rural / Urban Municipality officials.

For further information 1. Chandra Gurung (District Coordinator) 2. (District Technical Officer) 3. Manisha Rai (District Information Management Officer)
9841478742 9842062006