

District Report

Sindhupalchok

17 - 30 August 2018

Summary of events during this period

Name of activity/event	Event date	Participants summary		Contact Person	Reference Document
		Male	Female		
Ward level coordination meeting in Barhabise UM	17 th August 2018	1	0	techcord.sindhupalchok@hrrpnepal.org	
Follow up Partner satisfaction survey Round 3				dc.sindhupalchok@hrrpnepal.org	
District level General Coordination meeting	22 nd August 2018	4	0	dc.sindhupalchok@hrrpnepal.org	
5W update	25 th August 2018			Im.sindhupalchok@hrrpnepal.org	
Participate in working session with Caritas Nepal	28 th August 2018	13	3		

Upcoming Events & Meetings

Name of activity/event	Date, Time, and Location	Organizer	Contact Person
18 district field visit orientation	31 st Aug 2018, 9:00	HRRP	dmt@hrrpnepal.org
Field movement to various districts by team	3 rd Sep 2018 onwards, Kaski, syangja, Palpa, Gulmi etc.	HRRP	dmt@hrrpnepal.org
District level General Coordination meeting	21 st Sep, 11:00 am- 1:00 pm, GMaLi office.	HRRP	dc.sindhupalchok@hrrpnepal.org
Ward level coordination meeting (Sanga chok gadhi)	28 th -29 th Sep, 2017	HRRP	dc.sindhupalchok@hrrpnepal.org

To include details of upcoming events and meetings in the next bulletin, please share details with dc.sindhupalchok@hrrpnepal.org by COB Wednesday of each week.

Field Visit /Joint Field Monitoring Visit Reports

Visit 1

Date	Location	Participants from HRRP and stakeholders
17 th -18 th Aug, 2018	Ward no.3,4 &8 of Barhabise UM	Pradip Sharma, NRA Engineer (Ujjal Basnet) and NRA Sub Engineer (Tarakanta Chaudhari) JICA Engineer Dipendra Thapa.
Objective(s)	To observe, supervise and monitor ongoing construction of Houses (Compliance & Non-Compliance houses) at Barhabishe Municipality Ward no.3, 4 & 8.	

Summary	Field Visit to ward no.3,4 & 8 of Barhabise UM: - The key issues and challenges are enlisted in detail on the meeting minute shared: https://drive.google.com/open?id=1-tF6MaLawXJME6YyhOHuSNHtMz5Df7vI - The Field visit report is enlisted in detail on the report shared: https://drive.google.com/open?id=19seOsPJVoV3WHBBuosRGG_TxMTT_3iFa		
Summary	Follow up Partner satisfaction survey Round 3 - Follow up on partner satisfaction survey with Partner organizations, Govt. agencies via email, phone and face to face meet with POs. - Ensured to fill the survey form within stipulated timeframe by POs. District Level General Coordination Meeting - The general updates of the reconstruction were shared by the Partner organization, DSE, engineers. - The key issues and challenges are enlisted in detail on the meeting minute shared: https://drive.google.com/open?id=172cbtEB_CuHdnQ6AWHwPrRGrAEVVbmx1 Participate in working session with Caritas Nepal - The meeting took place in HRRP office, Jwagal Lalitpur and focused on the following agendas. - Caritas Nepal to share progress of shelter work and gist of SWC evaluation; - District HRRP to share update on their work for past quarter and plan for upcoming quarter. - District Teams to share and discuss management /Operations concerns and issues with Caritas, including their possible solutions. - The meeting was carried out in good environment. The Caritas and district HRRP teams shared the presentation slide of the progress as of now. https://drive.google.com/open?id=1qikvEKROn2s_vzAXTF0ywnS33jNs5HaK - The management/operations concern and issues will be addressed said by Caritas PM, Mr. Manindra Malla.		
Challenges / Issues Identified	Action Required	Responsible	Timeframe
Water scarcity hindering the construction of buildings at Upper Barhabishe.	Proper water source is to be identified.	NGO working in WASH sector, Ward chief, GMALI.	ASAP
Very Slow Process from District Forest Office in approval of wood to the beneficiaries.	Ward and RM office need to insist DFO for the fast pace approval.	Ward chief, RM chairman and DFO.	ASAP.

Photos



District level coordination meeting being held at Field training center, Chautara. Photo taken by Pranjal Bhandari.



GMALI chief Mr. Madhav Jung Karki answering reconstruction queries in DCM meeting. Photo taken by Pranjal Bhandari


Housing Typology Report



Tulashi Kumar Basnet residence of Barhabishe ward no.8, 2nd tranche received and 3rd Tranche also received, Stone Masonry with cement mortar ,the house is complete ready to receive completion certificate



Mr. Subba Tamang, residence of Barhabishe ward no. -03, had constructed a Load Bearing Structure (Brick masonry in Cement Mortar)and received all three tranches.



The house belongs to Padam Bahadur Basnet residence of Barhabishe and 2nd tranche of the house has been received a Load Bearing Structure (Stone masonry in Cement Mortar. Proper used band.



Antari Tamang, the house owner, had received first Tranche but not approve for Second Tranche. The house located at Barhabishe ward no.- 03, Sindhupalchok. It is a under construction up to corner band load Bearing Building before earthquake but now it's just a one storey with CGI sheet roofing house owner said that.