

District Report

Kathmandu Valley

22 June - 5 July 2018

Summary of events during this period

Name of activity/event	Event date	Participants summary		Contact Person	Reference Document
		Male	Female		
HRRP Kathmandu Valley Team along with HRRP's Recovery Advisor, Siobhan Kennedy and Maggie Stephenson, Senior Technical Advisor, UN-Habitat visited Sankhu area, Shankharapur Municipality, Kathmandu to observe the scenario of urban reconstruction.	22 June 2018	1	4	Ms. Sweata Sijapati, District Technical Coordinator, HRRP Kathmandu Valley tech.coord@hrrpnepal.org	
HRRP Kathmandu Valley Team organized an Orientation Program on Light Timber/Steel Frame Structure Manual at Dhokaima Café, Patan Dhoka, Lalitpur. The orientation program was targeted to equip the technical staffs of DLPIU, Rural/Urban Municipality and Partner Organizations who have been working in housing sector in Kathmandu valley about various aspects of shelter construction using light timber/steel frame. Similarly, key findings from the joint monitoring visits that are organized in coordination with M & E Consultant, CLPIU NRA Building, were also presented along with key features of information management products of HRRP. Key contents of the light timber/steel frame manual included the following- ➤ The background on light timber/steel frame structure, its technical specifications, applicability, construction practices and correction measures. ➤ Light steel frame structure basically refers to use of steel sections similar as use of rebar in load bearing structure. It does not mean to moment resisting steel frame structures. ➤ 6 case studies pertaining to the usage of different frames in light timber/steel frames were also discussed. ➤ This manual has certain limitations and is only relevant for residential buildings and fall under category 'C' and 'D' of Nepal Building Code. Technical specifications included key evaluation/inspection items, minimum requirements in shape and size	25 June 2018	18	26	Ms. Ambika Amatya, District Coordinator, HRRP Kathmandu Valley dc.ktm@hrrpnepal.org	

Summary of events during this period

of buildings, materials, foundation, frame action, connection and joint and roof structure.					
HRRP Kathmandu Valley Team visited 6 municipalities with a purpose of conducting follow up for reconstruction status of verification of vulnerable beneficiaries. The visited local bodies were Madhyapur Thimi, Suryabinayak, Bhaktapur, Changunarayan Municipalities, Lalitpur Metropolitan City and Kathmandu Metropolitan City. Similarly, the team also visited NRA DLPIU GMaLI offices of Kathmandu and Bhaktapur districts.	2 -4 July, 2018		2	Ms. Ambika Amatya, District Coordinator, HRRP Kathmandu Valley dc.ktm@hrrpnepal.org	
HRRP Kathmandu Valley Team made rigorous follow up contact with entire municipalities in the Kathmandu valley with a purpose of conducting follow up for reconstruction status of verification of vulnerable beneficiaries.	2 -4 July, 2018		3	Ms. Manisha Rai, IM Officer HRRP Kathmandu Valley im.ktm@hrrpnepal.org	

Upcoming Events & Meetings

Name of activity/event	Date, Time, and Location	Organizer	Contact Person
Monthly Coordination Meeting of Bhaktapur district	06 July 2018 (22 Shrawan 2075) NRA DLPIU GMaLI Bhaktapur Office, Bhaktapur district	NRA DLPIU GMaLI Bhaktapur	Mr. Bhoj Raj Bhatt MIS specialist Contact: 9851214538 bhojrajbhatt1@gmail.com
HRRP Kathmandu Valley Team to conduct visits with local bodies in Kathmandu valley with a purpose of follow up for reconstruction status of verification of vulnerable beneficiaries.	2 nd week of July 2018 Places: TBD	HRRP Kathmandu Valley Team	Ms. Ambika Amatya District Coordinator, HRRP Kathmandu Valley Team dc.ktm@hrrpnepal.org
Monthly Coordination Meeting of Lalitpur district	19 July 2018 (3 Shrawan 2075), NRA DLPIU GMaLI Lalitpur Office, Lalitpur district	NRA DLPIU GMaLI Lalitpur	Mr. Yamnath Giri M & E Specialist, NRA DLPIU GMaLI Lalitpur Contact: 9851239785 yamnathgiri2014@gmail.com
Joint Monitoring Visit by team including of M & E Consultant, CLPIU NRA Building and HRRP Kathmandu Valley to various parts of Kathmandu valley	2 nd week of July 2018 Places: TBD	CLPIU NRA Building and HRRP Kathmandu Valley Team	Ms. Sweata Sijapati District Technical Coordinator, HRRP Kathmandu Valley techcord.ktm@hrrpnepal.org
Orientation on 5W update to POs	3 rd week of July 2018	HRRP- Kathmandu Valley team	Ms. Manisha Rai, IM Officer HRRP Kathmandu Valley im.ktm@hrrpnepal.org

To include details of upcoming events and meetings in the next bulletin, please share details with dc.ktm@hrrpnepal.org by COB Wednesday of each week.

News & Updates

Reconstruction updates of Bhaktapur district (as of 04 July 2018)

Municipality	Total beneficiaries	PA agreement	1st tranche received	2nd tranche received	3rd tranche received	Total beneficiaries in retrofitting list	Retrofitting 1st tranche received
Bhaktapur	7619	5467	5467	1104	778	145	5
Changunarayan	10934	9352	9352	1634	1539	207	19
Madhyapur Thimi	2333	2000	2000	336	259	93	25
Suryabinayak	7416	6747	6747	1264	1153	227	0
Total	28302	23566	23566	4338	3729	672	49

Field Visit

Visit 1

Date	Location	Participants from HRRP and stakeholders
2 July 2018	Lalitpur Metropolitan City, Lalitpur District	Ambika Amatya and Manisha Rai (HRRP Kathmandu Valley Team)
4 July 2018	Changunarayan Municipality, Bhaktapur District Bhaktapur Municipality, Bhaktapur District Madhyapur Thimi Municipality, Bhaktapur District Suryabinayak Municipality, Bhaktapur District Kathmandu Metropolitan City, Kathmandu District	

Objectives	To conduct follow up with focal person of the administrative department regarding reconstruction status verification of vulnerable beneficiaries.
------------	---

Summary	HRRP Kathmandu Valley Team Lalitpur Metropolitan City on 2 July 2018 and 4 municipalities of Bhaktapur districts namely Suryabinayak, Changunarayan, Madhyapur Thimi and Bhaktapur and Kathmandu Metropolitan City on 4th July 2018 for the follow up on the reconstruction status of the vulnerable beneficiaries. The team met with the focal person from the administrative department along with DLPIU deployed engineer for the update on the verification of the vulnerable beneficiaries as requested by NRA GMaLI of respective districts. HRRP also requested everyone for their support in conducting follow up with ward offices for the verification of vulnerable households' list as soon as possible. During the visit it was found that some of the municipalities had not dispatched the letter to ward level so request were made to send the official letter and beneficiaries list at earliest possible. The team also collected the names and contact details of ward representatives for further follow up on the reconstruction status verification process at local level.
---------	---

Challenges / Issues Identified	Action Required	Responsible	Timeframe
Slow responses from concerned ward offices in reconstruction efforts could further delay in	Regular coordination needs to be conducted with local representatives for the timely	NRA DLPIU GMaLI office, concerned local bodies, HRRP	As early as possible or by

meeting the target of reconstructing houses for vulnerable beneficiaries.	verification of reconstruction status of vulnerable beneficiaries. HRRP should further support the follow up process with local bodies.		end of Ashad 2075
---	--	--	-------------------

Housing Typology Report



Ward no. 5, Lachhi, Kirtipur Municipality, Kathmandu. BMC structure, 2 room house with flexible roof with target of 2.5 storey. The eccentric footing in the load bearing structure and no vertical reinforcement in the openings make the structure non-compliance. Beneficiary has received 1st tranche and further correction measure and analysis were suggested for the house to be eligible for the remaining tranche.



Beneficiary Name: Kanchu Maya Lama, Ward no. 1, Gagalphedi, Kageshwori Manahara Municipality, Kathmandu. Single storey, 2 roomed BMC structure with flexible roof. The house is in process of getting building permit which has delayed in getting the 2nd tranche. The house falls under non-compliance due to missing bands such as sill band, lintel band and roof band. The beneficiary has agreed to add missing earthquake resistant elements after receiving the second tranche.

Questions Collected

Question	Who Asked the Question?	Response Provided (By Whom)
How to use timber in retrofitting purposes particularly in historic buildings, temples and monuments?	Engineer, POs	Proper technical assessment of historical monuments and religious structures should be done in order to use timber or steel frame. The preparation of provisions mentioned in light timber/steel frame manual has followed the Nepal Building Code, so usage of timber/steel should make a base with the standard code. Use of fresh and new timber is highly recommended in order to eliminate deterioration capacity of old timber. (National Technical Coordination Officer , HRRP)
How to move forward with use of timber in confined masonry cases?	Engineer, POs	There are certain pros and cons of using timber in confined masonry. Proper testing and technical assessment should be done. Use of new timber is highly recommended. The masonry walls are constructed within the plane of the framing as confined. Here, the masonry infill wall is used as the shear wall panel. The walls are built tight to the

Questions Collected

		columns, top and bottom of the wall. (National Technical Coordination Officer , HRRP)
--	--	---

Challenges and Way Forward

Challenge	Way Forward
Delays in correspondence from local bodies regarding verification of reconstruction status of vulnerable households could contribute in further delay of shelter reconstruction target.	Concerned urban/ rural municipalities should proactively take forward coordination with local ward office for verification of reconstruction status of vulnerable households. Follow up should be made from the concerned focal points in urban/rural municipalities for as early as possible verification process.