


FACTS AND FIGURES



Damage Status - Private Structures

MAJOR HOUSING TYPOLOGIES

Typology	Municipal	District
Stone and Mud Mortar Masonry	98.01%	97.73%
Timber Frame Structure	0.78%	0.37%
Brick and Cement Mortar Masonry	0.35%	0.17%
Stone and Cement Mortar Masonry	0.27%	0.46%
Others	0.60%	1.28%

CBS damage assessment survey, 2015

HOUSING RECONSTRUCTION & RETROFIT UPDATES

Reconstruction Status

Total Eligible HHs	6,343
PA Agreement	6,075
I st Tranche received	6,066
II nd Tranche received	5,203
III rd Tranche received	4,294

Houses

Under Construction: -

Completed: -

Retrofitting Status

Total Eligible HHs	347
PA Agreement	1
I st Tranche received	1
II nd Tranche received	347

Grievances

Registered: 1,031

Addressed: 1,031

Non-compliances

Registered: -

Addressed: -

Data Updated on: 2019-05-29 00:00:00

P0 Presence

Active: No POs Reported

Phased Out: CSIDB (Shelter), FRADS-N (Education), GOAL (Shelter), GON - DUDBC (Shelter), GON-PAF (Shelter), HELVETAS (Shelter), HI (Shelter), NRA (Shelter), PIN (Shelter), SABAL (Shelter), SCI (Education), SCI (Social Protection)

STATUS OF CONSTRUCTION MATERIALS

Materials	Unit	Req. Quantity*	Ava.	Cost (NRs.)**
Stone	m ³	114,669	Y	-
Aggregate	m ³	117,305	Y	-
Sand	m ³	12,240	Y	-
Timber	cu. ft.	14,110	Y	-
Cement (PPC)	Sack	-	-	-
Cement (OPC)	Sack	388,017	Y	-
Rebars	kgs.	1,242,548	-	-
Tin	bundle	15,853	-	-
Bricks	pcs.	1,046,684	Y	-

Types of Workers

1. Skilled mason
2. Labourer

Avg. daily wage (NRs.)

-/-
-/-

OTHER SECTORS



Schools

Damaged: 50
Under Construction: 31
Construction Completed: 31



Health Posts

Damaged: -
Under Construction: -
Construction Completed: -

KEY CONTACTS

Municipal Office

Khadga Bahadur Sunuwar
Chairman
9851171325

Municipal Office

Ekraj Bista
Focal Person
9842520398

Municipal Office

Radhika Shrestha
Deputy Chairman
9744039057

GMaLI/NRA

NRA Chief-District
0

Municipal Office

Shiv Kumar Rai
Chief Administration Officer
9854043640

DLPIU-Building

Prabhakar Lal Karna
DUDBC.DLPIU Chief
9854041543

HHs WITH LAND ISSUES

No Reported Land Issues

STATUS OF TECHNICAL STAFF


Staff	Available Nos.	Additional Req. Nos.
Engineers	-	-
Sub-Engineers	-	-
Asst. Sub-Engineers	-	-
Masons	- (7 days) - (50 days)	- (7 days) - (50 days)

Source: Municipal survey

MASON TRAINING


Trainings (# out of total required)

7 days Training



Reached


50 days Vocational Training



Remaining

Source: HRRP Analysis

TA ACTIVITIES MAP



FAQs

Q: What documents are required for enrolment in the GoN housing reconstruction programme?

A: Two copies of passport size photos and original copy and photocopy of land ownership card and citizenship card. Local officials at the Rural / Urban Municipality will be able to provide information and support and households can enrol at the Rural / Urban Municipality.

Q: Do we need to pay the engineers when they come to conduct inspections or provide technical assistance?

A: No, you do not have to pay the engineers, or any other staff, conducting inspections or providing technical assistance. If any field staff request payment for conducting inspection or providing technical assistance you should report it to the Rural / Urban Municipality officials.

For further information

1. Prabin Gautam (District Coordinator)
9860687776

2. Tulasi Ram Lamichhane (District Technical Officer)
9851213610

3. Pranjal Bhandari (District Information Management Officer)
9840057752