




Boundaries

- International
- District
- Gaupalika/Nagarpalika

National Park/Wildlife Reserve

Damage Levels (Percent)

- Area with access to Technical Assistance
- 1% - 40%
- 41% - 60%
- 61% - 80%
- 81% - 90%
- 91% - 100%


Note:

This highlighted area represent the VDC which have not received any form of technical assistance as per HRRP 4W – R46, with an overlay on the percent of Damaged (Grade III – V) structures per VDC.

Kindly refer to the map TA-ActivityAnalysis-ID0509 for more details regarding the gaps highlighted in this map.

Map Doc Name: TA-DamageOverlay-ID0508
GLIDE Number: EQ-2015-000048-NPL
Creation Date: 16 Jan, 2018

Map Data Source: HRRP_4W_R46, NRA
Geo Data Source: DoS, MoFALD;
Web Resource: www.hrrpnepal.org



Disclaimer: The boundaries and names shown and the designations used on this map do not imply official endorsement or acceptance by HRRP.

