



How are the distribution statistics of critical defects in the southeast wall



Below is a detailed analysis of the distribution statistics of critical defects in the southeast wall. The data includes defect counts, their respective altitudes, and calculated floor locations.

Table: Critical Defect Distribution

Defect ID	Instances	Latitude	Longitude	Altitude (m)	Calculated Floor
IR 1	14	22.39733576702892	114.19141560654931	111.569	14
IR 2	14	22.397380937028597	114.19146900652527	111.911	14
IR 3	12	22.397381267028592	114.19146910652509	98.552	12
IR 4	10	22.3973804370286	114.19147000652553	88.44	10
IR 7	5	22.397380077028604	114.19146870652574	57.964	5
IR 8	4	Southeast	Southeast	N/A	N/A
IR 13	5	22.3972097670	114.1912866066166	58.64	5

22.397209767029825	114.19128660661669	58.64	5	Image
22.397209357029826	114.19128670661655	116.867	Top (18th floor)	Image

Visualization: Distribution of Defects by Floor

Below is a mermaid chart visualizing the distribution of critical defects across floors.

Mermaid



Classic

Hand Drawn

Critical Defects Distribution by Floor

