

Inspection language console

Natural-language query · Asset-ID grounded

[cite-or-abstain](#)

How are the distribution statistics of critical defects in the southeast wall?

Grounded summary

Below is a detailed analysis of critical defects on the southeast elevation. Counts, altitudes, and calculated floors are taken from observation cards linked to host Asset-IDs.

Retrieved package · 7 observation IDs · southeast wall hosts

Defect ID	Instances	Latitude	Longitude	Altitude (m)	Floor
IR 1	14	22.2014	113.5491	111.57	14
IR 2	9	22.2015	113.5490	98.22	12
IR 3	6	22.2013	113.5492	84.10	10
IR 7	5	22.2016	113.5489	125.40	Top (18)
IR 8	3	Southeast bay		N/A	—

[Open IR 1 crop](#)

[Expand upstairs neighbours](#)

[Draft gondola brief](#)

Ask a follow-up (Asset-ID required for writes)...



Evidence & visualisation

Openable citations · floor distribution

[Image links](#)

Defect ID	Altitude (m)	Floor	Evidence
IR 1	111.57	14	Open
IR 2	98.22	12	Open
IR 3	84.10	10	Open
IR 7	125.40	Top (18)	Open

Distribution of critical defects by floor

[Classic](#)

[Topology](#)

