


Façade analysis


430

Total defects detected (campaign)


By category



Type mix



3D twin viewer - Asset-ID markers



Language panel

Aggregated 11 unique critical delamination defects with floor, quantity, and altitude from twin records:

ID	n	Floor	Alt (m)
IR-1	14	14	111.6
IR-2	9	12	98.2
IR-3a	4	10	84.1
IR-7	5	Top	125.4

Open IR-1

Expand neighbours

Talk to inspection copilot...

