

Full Inspection Report

Total Inspected: 2 No Defect: 1 Defect: 1


Inspection #1

Product ID	P-C71828
Inspection Date	2026-06-13 16:46:12
Status	Healthy
Defect Type	None
Confidence Score	100.0%



Inspection #2

Product ID	P-82753E
Inspection Date	2026-06-13 16:45:53
Status	Defective
Defect Type	Corrosion
Confidence Score	81.78%



Need help understanding the results?

If you need any help or have a question, you can contact the AI Chat inside the system.