

PRIVATE annual review

permit year 2025

resident personal phone 555-0172

contractor dispute and legal settlement note included

Outfal 07 -> Outfall 07

E. coli 410 -> E. coli 140

Corrective action due 2026-09-01 -> 2026-08-25

Green roof area 18,000 sq ft -> 18,800 sq ft

permit year 2025 -> 2026

Overall status | Substantial compliance

Public monitoring locations | 8 active outfalls

Corrective actions closed | 5 of 6

Public complaint response target | 3 business days

scratch: enforcement strategy not public

Permit milestone	Public due date	Status
Annual report submission	2026-10-15	Complete
Dry-weather screening	2026-07-31	Complete
Public education campaign	2026-09-20	Complete
Illicit discharge training	2026-08-12	Complete

Outfall	Parameter	Result	Public Threshold	Status
Outfal 07	E. coli	410	235	Exceeds threshold
Outfall 12	Turbidity	7 NTU	10 NTU	Within threshold
Outfall 18	pH	7.4	6.5-8.5	Within threshold
unverified lab note: rerun sample privately				

enforcement strategy

contractor dispute

resident personal phone 555-0172

legal settlement note

do not release

Action ID	Corrective Action	Public Due Date	Owner	Status
CA-001	Repair sediment control at Maple Yard	2026-09-01	Field Operations	Open
CA-002	Replace damaged inlet marker set	2026-08-28	Public Works	Complete
CA-003	Update contractor spill checklist	2026-09-05	Compliance Office	Open

Complaint ID | Public Category | Received | Response Status

PC-001 | Odor report near West Creek | 2026-06-03 | Closed

PC-002 | Sediment tracking near Maple Yard | 2026-07-18 | Closed

PC-003 | Standing water near school route | 2026-08-02 | Closed

PC-004 | Storm drain marking request | 2026-08-19 | In progress

Asset	Location	Public Quantity	Maintenance Status
Bioretention cells	Civic Center	14	Current
Green roof area	Library Annex	18,000 sq ft	Current
Permeable pavement	Depot Lot	42,500 sq ft	Current
Tree trench segments	River Avenue	11	Current

QA Item | Required Public State

Chain-of-custody forms complete | Yes

Lab duplicate within tolerance | Yes

Field blank reviewed | Yes

Corrected values verified | No

unverified lab note | do not release

Style element | Public requirement

Header band height | 40 points

Cover and appendix color | 243B53

Summary and permit color | 007C89

Monitoring and QA color | 2E7D32

Corrective action color | C55A11

Complaint log color | 7030A0

Register field | Public value

Appendix A | Monitoring method summary

Appendix B | Public complaint category definitions

Appendix C | Green infrastructure asset list

Release approval | Water Quality Director

PRIVATE legal hold appendix withheld