

Fell job number	Tree position	Road Name	Existing tree species
12019850	Outside 2	Abbeydale Park Rise	Tibetan Cherry
12019853	Outside 3	Abbeydale Park Rise	Tibetan Cherry
12014486	Outside 9	Abbeydale Park Rise	Tibetan Cherry
12019856	Outside 6-8, between	Abbeydale Park Rise	Tibetan Cherry
12018163	Outside 20	Abbeydale Park Rise	Tibetan Cherry
12019858	Outside 22-24, between	Abbeydale Park Rise	Tibetan Cherry
12019860	Outside 30-32, between	Abbeydale Park Rise	Tibetan Cherry
12019883	Outside 39	Abbeydale Park Rise	Tibetan Cherry
12019872	Outside 95	Abbeydale Park Rise	Rowan
12006353	Outside 83	Abbeydale Park Rise	Tibetan Cherry
12019870	Outside 64	Abbeydale Park Rise	Tibetan Cherry
12019874	Outside 75	Abbeydale Park Rise	Tibetan Cherry
12019862	Outside 36	Abbeydale Park Rise	Tibetan Cherry
12019878	Outside 51-53, between	Abbeydale Park Rise	Tibetan Cherry
12019876	Outside 55	Abbeydale Park Rise	Tibetan Cherry
12019866	Outside 42-44	Abbeydale Park Rise	Tibetan Cherry
12019864	Outside 38	Abbeydale Park Rise	Tibetan Cherry
12019881	Outside 49	Abbeydale Park Rise	Tibetan Cherry
12019868	Outside 56-58, between	Abbeydale Park Rise	Tibetan Cherry
12019931	Outside 8	Ashfurlong Close	Kanzan Cherry
12019933	Outside 9	Ashfurlong Close	Kanzan Cherry
12019927	Outside 4	Ashfurlong Close	Kanzan Cherry
12019929	Outside 6	Ashfurlong Close	Kanzan Cherry
12019923	Outside 3	Ashfurlong Drive	Apple species
12019925	Outside 20	Ashfurlong Drive	Apple species
12019919	Outside 18	Ashfurlong Road	Kanzan Cherry
12019917	Outside 8	Ashfurlong Road	Kanzan Cherry
12019913	Outside 33, (bottomside, closer to driveway 1 of 2)	Ashfurlong Road	Apple species

12019921	Outside 20 (topside, upper most 1 of 2 Outside 20)	Ashfurlong Road	Kanzan Cherry
12019915	Outside 6	Ashfurlong Road	Kanzan Cherry
12019745	Outside 18	Blacka Moor Crescent	Whitebeam
12019747	Outside 52	Blacka Moor Road	Kanzan Cherry
12019685	Outside 1	Brinkburn Vale Road	Common Lime
12019689	Outside 2	Brinkburn Vale Road	Common Lime
12019687	adjacent 2	Brinkburn Vale Road	Common Lime
12019691	Outside 2	Brinkburn Vale Road	Common Lime
12019693	Outside 6	Brinkburn Vale Road	Common Lime
12019907	Outside 18	Burlington Road	Hawthorn
12019905	Outside 21	Burlington Road	Tibetan Cherry
12019903	Outside 33	Burlington Road	Tibetan Cherry
12019911	Outside 42	Burlington Road	Tibetan Cherry
12019909	Outside 40	Burlington Road	Tibetan Cherry
12019901	Opposite 50	Burlington Road	Apple species
12013988	Outside 99	Bushey Wood Road	Rowan sp
12019789	Outside 43	Bushey Wood Road	Rowan
12019791	Outside 26	Bushey Wood Road	Rowan
12019785	Outside 62	Bushey Wood Road	Kanzan Cherry
12014074	Outside 114	Bushey Wood Road	Rowan sp
12019783	Outside 40	Bushey Wood Road	Apple species
12019787	Outside 68	Bushey Wood Road	Kanzan Cherry
12018065	Outside 122	Bushey Wood Road	Rowan sp
12019711	Outside 33	Chatsworth Road	Common Lime
12019713	Outside 35	Chatsworth Road	Common Lime
12019719	Outside 49	Chatsworth Road	Common Lime

12019721	Outside 51	Chatsworth Road	Common Lime
12019715	Outside 43	Chatsworth Road	Common Lime
12019717	Outside 47	Chatsworth Road	Common Lime
12019709	Outside 31	Chatsworth Road	Common Lime
12006903	Facing corner of 4, (Outside 4-6)	Devonshire Drive	Tibetan Cherry
12019897	OPP 2, (first tree on road, at side of 82)	Devonshire Drive	Tibetan Cherry
12006905	Outside 10	Devonshire Drive	Tibetan Cherry
12019899	Outside 12-14, between	Devonshire Drive	Tibetan Cherry
12019895	Outside 59	Devonshire Road	Rowan
12006899	Outside 73	Devonshire Road	Tibetan Cherry
12019893	Outside 67, (lowermost 1 of 2 trees Outside 67)	Devonshire Road	Cherry species
12019887	Outside 78A	Devonshire Road	Tibetan Cherry
12019889	Outside 86	Devonshire Road	Swedish Whitebeam
12019891	Outside 90	Devonshire Road	Tibetan Cherry
12019886	OPP 57A	Devonshire Road	Cherry species
12006897	Outside 57A	Devonshire Road	Cherry species
12019823	Outside 93	Furniss Avenue	Rowan sp
12019813	Outside 76	Furniss Avenue	Kanzan Cherry
12019815	Outside 114	Furniss Avenue	Rowan sp
12019817	Outside 118	Furniss Avenue	Kanzan Cherry
12019819	Outside 132	Furniss Avenue	Kanzan Cherry
12019805	Outside 24	Furniss Avenue	Kanzan Cherry
12019827	Outside 57-59	Furniss Avenue	Kanzan Cherry
12019825	Outside 83	Furniss Avenue	Kanzan Cherry
12019811	Outside 58	Furniss Avenue	Kanzan Cherry
12019809	Outside 40	Furniss Avenue	Kanzan Cherry
12019801	Outside 6	Furniss Avenue	Kanzan Cherry
12019833	Outside 17	Furniss Avenue	Kanzan Cherry
12019831	Outside 29	Furniss Avenue	Kanzan Cherry
12011449	Outside 49	Furniss Avenue	Kanzan Cherry

12010182	Outside 39	Furniss Avenue	Kanzan Cherry
12019829	Outside 35-37	Furniss Avenue	Kanzan Cherry
12010192	Outside 92	Furniss Avenue	Rowan sp
12019807	Outside 34	Furniss Avenue	Kanzan Cherry
12010194	Outside 98	Furniss Avenue	Rowan sp
12019821	Outside 131	Furniss Avenue	Kanzan Cherry
12019803	Outside 12	Furniss Avenue	Kanzan Cherry
12013582	Outside 11	Heather Lea Avenue	Swedish Whitebeam
12019733	Outside 53	Heather Lea Avenue	Kanzan Cherry
12019731	Outside 43	Heather Lea Avenue	Kanzan Cherry
12019729	Outside 10/12	Heather Lea Avenue	Swedish Whitebeam
12009545	Opposite 25	Kerwin Road	Rowan sp
12019723	Outside 19	Kerwin Road	Kanzan Cherry
12019725	Outside 17	Kerwin Road	Rowan sp
12019727	Outside 2 (lowermost 1 of 2 trees Outside 2)	Kerwin Road	Rowan sp
12019841	Outside 21	King Ecgbert Road	Kanzan Cherry
12019844	Outside 38 (opposite 37)	King Ecgbert Road	Kanzan Cherry
12019848	Outside 49	King Ecgbert Road	Kanzan Cherry
12019846	Outside 63	King Ecgbert Road	Kanzan Cherry
12019654	Outside 29-31	Marstone Crescent	Kanzan Cherry
12019660	Outside 75	Marstone Crescent	Apple species
12019662	Outside 77	Marstone Crescent	Kanzan Cherry
12019666	Outside 6	Marstone Crescent	Kanzan Cherry
12019650	Outside 23	Marstone Crescent	Kanzan Cherry
12019656	Outside 43	Marstone Crescent	Kanzan Cherry
12019648	Outside 5	Marstone Crescent	Kanzan Cherry
12019664	Outside 69	Marstone Crescent	Kanzan Cherry
12019658	Outside 30	Marstone Crescent	Kanzan Cherry
12019652	outside 14	Marstone Crescent	Cherry
12019735	Outside 29	Newfield Crescent	Kanzan Cherry

12009310	Outside 4	Newfield Crescent	Rowan
12019769	Outside 17	Old Hay Close	Kanzan Cherry
12019773	Outside 76	Old Hay Close	Apple species
12019767	Outside 9 (opp 36)	Old Hay Close	Kanzan Cherry
12008872	Outside 34	Old Hay Close	Kanzan Cherry
12019771	Outside 33	Old Hay Close	Kanzan Cherry
12019775	Outside 78	Old Hay Close	Apple species
12019777	Outside 26	Old Hay Close	Kanzan Cherry
12019779	Outside 1	Old Hay Close	Kanzan Cherry
12019781	Side of 3 Old Hay Lane, ON Old Hay Close	Old Hay Close	Kanzan Cherry
12019739	Outside 11	Rushley Close	Kanzan Cherry
12019741	Outside 12	Rushley Close	Swedish Whitebeam
12019737	Side of 89 Rushley Rd	Rushley Close	Cherry species
12019743	Outside 11-13	Rushley Drive	Kanzan Cherry
12019671	Outside 25-27	Stonecroft Road	Rowan sp
12019676	Outside 37-39	Stonecroft Road	Rowan sp
12019678	Side of 44 Marstone Cres, tree on Stonecroft Road	Stonecroft Road	Apple species
12019680	Side of 42 Marstone Cres, tree on Stonecroft Road	Stonecroft Road	Kanzan Cherry
12019943	Outside 26	The Grove	Kanzan Cherry
12019945	Outside 60	The Grove	Common Ash
12019941	Outside 2	The Grove	Kanzan Cherry
12019951	Outside 1	The Grove	Kanzan Cherry
12019949	Outside 3	The Grove	Kanzan Cherry
12019947	Outside 7	The Grove	Kanzan Cherry
12019935	Outside 45	The Quadrant	Common Laburnum
12019939	Outside 21b	The Quadrant	Kanzan Cherry

12019937	Outside 23A	The Quadrant	Kanzan Cherry
12019799	Outside 126	Totley Brook Road	Common Lime
12019793	Outside 88	Totley Brook Road	Common Lime
12019795	Outside 90	Totley Brook Road	Common Lime
12019797	Outside 100	Totley Brook Road	Common Lime
12018112	Outside 55	Townhead Road	European Beech
12010508	Outside 107	Townhead Road	Willow
12019695	Outside 1	Vernon Road	English Oak

Reason for Removal	Replant species
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Structural Integrity	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Structural Integrity	Hawthorn
Decay	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Structural Integrity	Hawthorn
Damage to Surface	Hawthorn
Senescent	Hawthorn
Structural Integrity	Hawthorn
Senescent	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Structural Integrity	Hawthorn

Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Cherry
Damage to Surface	Cherry
Damage to Surface	Canadian Maple - October Glory
Damage to Surface	Canadian Maple - October Glory
Damage to Surface	Canadian Maple - October Glory
Damage to Surface	Canadian Maple - October Glory
Damage to Surface	Canadian Maple - October Glory
Decay	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Not Known
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Unauthorised removal	Mountain Ash
Structural Integrity	Mountain Ash
Structural Integrity	Mountain Ash
Carriageway Obstruction	Mountain Ash
Senescent	Mountain Ash
Damage to Surface	Mountain Ash
Decay	Mountain Ash
Structural Integrity	Hawthorn
Damage to Surface	Lime
Damage to Surface	Lime
Damage to Surface	Lime

Damage to Surface	Lime
Damage to Surface	Lime
Damage to Surface	Lime
Damage to Surface	Lime
Decay	Hawthorn
Damage to Surface	Hawthorn
Dead	Hawthorn
Damage to Surface	Hawthorn
Structural Integrity	Mountain Ash
Decay	Mountain Ash
Damage to Surface	Mountain Ash
Damage to Surface	Mountain Ash
Carriageway Obstruction	Mountain Ash
Damage to Surface	Mountain Ash
Damage to Surface	Mountain Ash
Decay	Mountain Ash
Decay	Hawthorn
Structural Integrity	Hawthorn
Decay	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Senescent	Hawthorn
Structural Integrity	Hawthorn
Structural Integrity	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Structural Integrity	Hawthorn
Structural Integrity	Hawthorn
Structural Integrity	Hawthorn

Decay	Hawthorn
Structural Integrity	Hawthorn
Decay	Hawthorn
Structural Integrity	Hawthorn
Decay	Swedish Whitebeam 'Brouwers'
Decay	Hawthorn
Senescent	Hawthorn
Structural Integrity	Canadian Crab
Structural Integrity	Canadian Crab
Structural Integrity	Canadian Crab
Structural Integrity	Canadian Crab
Senescent	Canadian Crab
Senescent	Canadian Crab
Structural Integrity	Canadian Crab
Damage to Surface	Mountain Ash
Damage to Surface	Mountain Ash
Structural Integrity	Mountain Ash
Damage to Surface	Mountain Ash
Structural Integrity	Hawthorn
Structural Integrity	Hawthorn
Structural Integrity	Hawthorn
Damage to Surface	Hawthorn
Structural Integrity	Hawthorn
Structural Integrity	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Failure	Hawthorn
Structural Integrity	Cherry

Structural Integrity	Cherry
Damage to Surface	Hawthorn
Structural Integrity	Not Known
Damage to Surface	Hawthorn
Structural Integrity	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Damage to Surface	Hawthorn
Structural Integrity	Hawthorn
Structural Integrity	Hawthorn
Damage to Surface	Canadian Crab
Damage to Surface	Canadian Crab
Damage to Surface	Canadian Crab
Damage to Surface	Canadian Crab
Damage to Surface	Canadian Crab
Structural Integrity	Hawthorn
Structural Integrity	Hawthorn
Decay	Hawthorn
Structural Integrity	Hawthorn
Damage to Surface	Canadian Crab
Damage to Surface	Canadian Crab
Damage to Surface	Canadian Crab
Damage to Surface	Canadian Crab
Damage to Surface	Canadian Crab
Damage to Surface	Canadian Crab
Structural Integrity	Canadian Crab
Damage to Surface	Canadian Crab

Damage to Surface	Canadian Crab
Damage to Surface	Lime
Damage to Surface	Lime
Damage to Surface	Lime
Damage to Surface	Lime
Structural Integrity	European Beech
Structural Integrity	Hawthorn
Damage to Surface	Canadian Maple - October Glory