

Work Order – WO-2026-04567

Linked CR: CR-2026-00123 | Linked SOP: SOP-AFW-001

Work Performed

Adjusted coupling alignment and verified vibration below alarm threshold.

[FIGURE PLACEHOLDER]

Figure 1: Coupling Alignment Measurement Results