

# Visual Inspection Assessment

## Church Details

Church Name: Santa Maria Church

Location: Santa Maria, Ilocos Sur

Building Capacity: Approximately 1,000 people

Date Built: 1765



---

## Damage Assessment

Vegetation Damage: 0

Water Damage or Mold: 0

Unfinished Paint: 1

Crack: 0

Sagging Roof: 0