



Pre Export Vehicle Appraisal

Certificate No. : 20210105-734280

Date of Issue : 06/01/2021

Vehicle Make : TOYOTA

Vehicle Model : WISH

Chassis No. : ZGE20-0018124

Authorization : *Takeshi Takasaki*



1. Appraisal Details:

Client Details: NEXCO JAPAN PTE LTD

Date & Time: 28/12/2020 02:54 PM

Inspector: Kunihiro Oba

Window Sticker: 734280

Location: YOKOHAMA, KANAGAWA

Weather: SUNNY

2. Vehicle Details:

Make: TOYOTA

Model: WISH

Year of Manufacture: 2009

Year of Registration: 200906

Body Type: STATION WAGON

Vehicle Type: Passenger

Colour: BLACK

Passenger Capacity: 7

Fuel Type: Petrol

Auction Report: No

Maintenance Record: No

BioDecontamination OK: Yes

Chassis/VIN No.: ZGE20-0018124

Engine Capacity: 1,790 cc/kw

Odometer: 74,454 km

Engine Number: 0449058

RHD/LHD Vehicle: RHD

Transmission: A/T

Drive: 2WD FF

Number of Doors: 5

Model Code: DBA-ZGE20W

Euro 4 Compliant: Yes
(Japan 05) DBA

Stolen: No

3. Description of major areas (Summary of page 3):

Exterior Appearance: OK

Interior Appearance: OK

Mechanical: OK

Structural: OK

Biosecurity: OK

EV HEV Battery: N/A

Glazing: OK

Lights: OK

Gauges: OK

Wheels: OK

Tyres: OK

Emission Test: OK

This appraisal report does not confer or guarantee acceptance by the Land Transport Authority Fiji for the vehicle importation and registration for use in Fiji.

Important Note:



For Terms & Conditions please see www.JEVIC.com

Japan Export Vehicle Inspection Center Company Limited

15 Daikoku-Futo, Tsurumi-Ku, Yokohama, Kanagawa Prefecture, Japan 230-0054

Telephone: (045) 521-8527 Facsimile: (045) 521-8510 Website: www.jevic.com



Pre Export Vehicle Appraisal

Certificate No. : 20210105-734280
Date of Issue : 06/01/2021
Vehicle Make : TOYOTA
Vehicle Model : WISH
Chassis No. : ZGE20-0018124
Window Sticker : 734280



4. Photographs



Front Left



Front Right



Audio Dashboard



Rear Left



Rear Right



Seats Front



Engine Bay



Underneath Front



Seats Rear



Boot



Underneath Rear



Additional



Pre Export Vehicle Appraisal

Certificate No. : 20210105-734280
Vehicle Make : TOYOTA
Vehicle Model : WISH

Date of Issue : 06/01/2021
Chassis No. : ZGE20-0018124
Window Sticker : 734280



5. Detailed description

Interior Equipment

Sunroof	No
Spare Key	No
Remote Key Lock	Yes
Power Steering	Yes
Tilt Steering	Yes
Cruise Control	No
Power Window(s)	Working
Central Locking	Working
Leather Seats	No
Power Seats	No
Heated Seats	No
Clearance Sonar	No
Air Conditioning	Yes
Audio Visual	Exist
Navigation	Yes
Radio	Yes
CD	Yes
DVD	Yes
iPod Link	No
SD Card	Yes
USB	No
HDMI	No
HIC	No
Other	
	N/A

Interior Condition

Interior Odour	None
Steering Wheel	Normal
Aftermarket	No
Gear Knob	Present
Aftermarket	No
Seat Driver	Normal
Aftermarket	No
Seat Passenger	Normal
Aftermarket	Yes
Seat Rear	Normal
Seat 3rd Row	Normal
Seat-Headrests	All Present
Floor Mats	4 or more
Carpets	Yes
Pedals	Normal
Condition	
Roof Lining	No Damage
Dashboard	No Damage
Instrument Panel	No Damage
Door Lining	Vinyl
Driver	OK
Passenger	OK
Rear Right	OK
Rear Left	OK
Hatch	OK

Mechanical

Gauge - Odometer	Working
Gauge - Fuel	Working
Gauge - Temp	Working
Gauge - Tach	Working
Warning Light(s)	OK
Warning Lights on	-
Horn	Working
Engine - Start	Yes
Engine - Idle	Smooth
Belt Noise	Not Present
Wipers(s) Front	Working
Wipers(s) Rear	Working
Washer(s) Front	Working
Washer(s) Rear	Working
Muffler Noise	Normal
Engine Oil	Normal
Condition	Normal
Brake Fluid	Normal
Condition	Normal
Oil Leak (Serious)	No
Open/Closing OK	
Drivers Door	OK
Passengers Door	OK
Rear Right Door	OK
Rear Left Door	OK
Boot/Hatch	OK
Bonnet	OK
Fuel Flap	OK
Glove Box	Yes

Side Mirrors	Automatic
Left Side	OK
Rear View Mirror	Normal
Right Side	OK
Lever - Wiper	Normal
Lever - Indicators	Normal
Lever - Lights	Normal
Switches - Lights	Normal
Switches - Audio	Normal
Switches - Aircon	Normal
Seat Belts	
Driver	OK
Passenger	OK
Rear Right	OK
Rear Left	OK
Rear Center	OK
3rd Seats	Working
Lights OK	
Headlights	OK
Tail	OK
Side	OK
Indicators	OK
Brake	OK
Reverse	OK
Fog	OK
Licence Plate	OK
Interior	OK
Other Lights Not Working	
	N/A
Window Condition	OK

Safety Equipment

Drivers Airbag	Yes
Passenger Airbag	Yes
Curtain Airbag	Yes
Knee Airbag	No
ABS System	Yes
Handicap Options	Yes
Spare Tyre	Yes
Tool Kit	Yes
Jack	Yes
Safety Triangle	No

Tyre(s)

Front Right Tread	3 mm
Front Right Type	A
Front Left Tread	4 mm
Front Left Type	A
Rear Right Tread	3 mm
Rear Right Type	A
Rear Left Tread	3 mm
Rear Left Type	A
Spare Tread	3 mm
Spare Type	B

Emission Test

CO < 1%	0
HC < 300ppm	2
Opacity < 50%	N/A

Exterior Equipment

Tinted Windows	Yes
Body Kit	Yes
Alloy Wheels	Yes
After-Market Electrical Items	N/A
Additional fittings	OK

HV EV Battery & Warnings



OBD Check	N/A
Error Code	No
Voltage DTC	N/A
Voltage Diff (v)	N/A
Resistance DTC	N/A
Temp DTC	N/A
SOC	N/A

Biosecurity

Exterior/Interior	OK
-------------------	----

*DTC = Diagnostic Trouble Code
*SOC = State of Charge

Vehicle Damage / Underside Inspection



A = Scratch
B = Bent
H = Hble

P = Painted
R = Rust
T = Tear

U = Dent
W = Wave
X = Damage