



Pre Export Vehicle Appraisal

Certificate No. : 20200624-730341

Date of Issue : 24/06/2020

Vehicle Make : HONDA

Vehicle Model : FIT

Chassis No. : GP5-3208039

Authorization : *Tatsuki Takasaki*



1. Appraisal Details:

Client Details: Nexco Japan Pte Ltd
Date & Time: 23/06/2020 10:04 AM
Inspector: Takuyori Amano
Window Sticker: 730341

Location: YOKOHAMA, KANAGAWA
Weather: CLOUDY

2. Vehicle Details:

Make: HONDA
Model: FIT
Year of Manufacture: 2015
Year of Registration: 201505
Body Type: STATION WAGON
Vehicle Type: Passenger
Colour: BLACK
Passenger Capacity: 5
Fuel Type: Hybrid
Auction Report: No
Maintenance Record: No
BioDecontamination OK: Yes

Chassis/VIN No.: GP5-3208039
Engine Capacity: 1,490 cc/kw
Odometer: 116,269 km
Engine Number: 4409696
RHD/LHD Vehicle: RHD
Transmission: A/T
Drive: 2WD FF
Number of Doors: 5
Model Code: DAA-GP5
Euro 4 Compliant: Yes
(Japan 05) DAA
Stolen: No

3. Description of major areas (Summary of page 3):

Exterior Appearance: OK
Interior Appearance: OK
Mechanical: OK
Structural: OK
Biosecurity: OK
EV HEV Battery: OK

Glazing: OK
Lights: OK
Gauges: OK
Wheels: OK
Tyres: OK
Emission Test: OK

This appraisal report does not confer or guarantee acceptance by the Land Transport Authority Fiji for the vehicle importation and registration for use in Fiji.

Important Note:



For Terms & Conditions please see www.JEVIC.com



Pre Export Vehicle Appraisal

Certificate No. : 20200624-730341
Date of Issue : 24/06/2020
Vehicle Make : HONDA
Vehicle Model : FIT
Chassis No. : GP5-3208039
Window Sticker : 730341



4. Photographs



Front Left



Front Right




Audio Dashboard



Rear Left



Rear Right




Seats Front



Engine Bay



Underneath Front



Seats Rear



Boot



Underneath Rear



Additional



Pre Export Vehicle Appraisal

Certificate No. : 20200624-730341
Vehicle Make : HONDA
Vehicle Model : FIT

Date of Issue : 24/06/2020
Chassis No. : GP5-3208039
Window Sticker : 730341



5. Detailed description

Interior Equipment

Sunroof	No
Spare Key	No
Remote Key Lock	Yes
Power Steering	Yes
Tilt Steering	Yes
Cruise Control	No
Power Window(s)	Working
Central Locking	Working
Leather Seats	No
Power Seats	No
Heated Seats	No
Clearance Sonar	No
Air Conditioning	Yes
Audio Visual	Exist
Navigation	Yes
Radio	Yes
CD	Yes
DVD	Yes
iPod Link	No
SD Card	Yes
USB	Yes
HDMI	No
HIC	No
Other	
TV	

Interior Condition

Interior Odour	None
Steering Wheel	Normal
Aftermarket	No
Gear Knob	Present
Aftermarket	No
Seat Driver	Normal
Aftermarket	No
Seat Passenger	Normal
Aftermarket	No
Seat Rear	Normal
Seat 3rd Row	N/A
Seat-Headrests	All Present
Floor Mats	4 or more
Carpets	Yes
Pedals	Normal
Condition	
Roof Lining	No Damage
Dashboard	No Damage
Instrument Panel	No Damage
Door Lining	
Driver	Vinyl
Passenger	OK
Rear Right	OK
Rear Left	OK
Hatch	OK

Mechanical

Gauge - Odometer	Working
Gauge - Fuel	Working
Gauge - Temp	N/A
Gauge - Tach	N/A
Warning Light(s)	OK
Warning Lights on	
-	
Horn	Working
Engine - Start	Yes
Engine - Idle	Smooth
Belt Noise	Not Present
Wipers(s) Front	Working
Wipers(s) Rear	Working
Washer(s) Front	Working
Washer(s) Rear	Working
Muffler Noise	Normal
Engine Oil	Normal
Condition	Normal
Brake Fluid	Normal
Condition	Normal
Oil Leak (Serious)	No
Open/Closing OK	
Drivers Door	OK
Passengers Door	OK
Rear Right Door	OK
Rear Left Door	OK
Boot/Hatch	OK
Bonnet	OK
Fuel Flap	OK
Glove Box	Yes

Side Mirrors	
Automatic	
Left Side	OK
Rear View Mirror	Normal
Right Side	OK
Lever - Wiper	Normal
Lever - Indicators	Normal
Lever - Lights	Normal
Switches - Lights	Normal
Switches - Audio	Normal
Switches - Aircon	Normal
Seat Belts	
Driver	OK
Passenger	OK
Rear Right	OK
Rear Left	OK
Rear Center	OK
3rd Seats	-
Lights OK	
Headlights	OK
Tail	OK
Side	OK
Indicators	OK
Brake	OK
Reverse	OK
Fog	N/A
Licence Plate	OK
Interior	OK
Other Lights Not Working	
N/A	
Window Condition	OK

Safety Equipment

Drivers Airbag	Yes
Passenger Airbag	Yes
Curtain Airbag	Yes
Knee Airbag	No
ABS System	Yes
Handicap Options	No
Spare Tyre	Repair kit
Tool Kit	Yes
Jack	Yes
Safety Triangle	No

Tyre(s)

Front Right Tread	3 mm
Front Right Type	A
Front Left Tread	3 mm
Front Left Type	A
Rear Right Tread	3 mm
Rear Right Type	A
Rear Left Tread	3 mm
Rear Left Type	A
Spare Tread	N/A
Spare Type	N/A

Emission Test

CO < 1%	0
HC < 300ppm	5
Opacity < 50%	N/A

Exterior Equipment

Tinted Windows	Yes
Body Kit	No
Alloy Wheels	No
After-Market Electrical Items	
N/A	
Additional fittings	
OK	

HV EV Battery & Warnings



OBD Check	OK
Error Code	No
Voltage DTC	N/A
Voltage Diff (v)	0.01
Resistance DTC	N/A
Temp DTC	N/A
SOC	0

Biosecurity

Exterior/Interior	OK
-------------------	----

*DTC = Diagnostic Trouble Code
*SOC = State of Charge

Vehicle Damage / Underside Inspection



A = Scratch
B = Bent
H = Hble

P = Painted
R = Rust
T = Tear

U = Dent
W = Wave
X = Damage