CAFM Project

Computer-Aided Facility Management - Service Request Handling
Operations Service Project | Jira Service Management

Prepared by	Inamul Hasan
Date	22 October 2026
Platform	Jira Service Management - Operations Service Project
Request type used	Report a system problem
Total work items in queue	20

Project Overview


This report documents how facility service requests are raised, tracked and closed in the CAFM system. It follows the ticket lifecycle in order: ticket creation, queue review, assignment and status tracking, work-in-progress updates, completion and customer reply, and the final overview of all work.

Ticket lifecycle covered

Step	Stage	What the screenshot shows
1	Ticket creation	New 'Report a system problem' request for a power outage (OPS form)
2	Queue - initial state	All open queue: 20 work items, all Open and Unassigned
3	Queue - after assignment	All open queue: items assigned and moved to working statuses
4	Work in progress	OPS-20 CCTV camera: internal note and customer-visible update
5	Completed with reply	OPS-19 rodent inspection: completed with internal note and reply
6	Completed ticket detail	OPS-2 AC drainage: completed, with full Details panel
7	All work overview	All work list with assignee, reporter, priority and status

Step 1 - Ticket Creation

Creating a new service request




Key details

- Request type: Report a system problem.
- Raised on behalf of: Inamul Hasan.
- Summary: Power Outage & Main DB Tripped - Office Floor 5.
- Description: Main distribution board tripped, affecting all power sockets and lighting on Floor 5.

Step 2 - Queue Review: Initial State

All open queue - 20 work items




Key details

- All items shown are in status Open and the Assignee column shows Unassigned.
- Visible tickets: OPS-21 Visitor Pass Printer Paper Jam - Reception Desk; OPS-20 CCTV Camera #14 Blind Spot Realignment; OPS-19 Rodent Inspection Request - Garbage Room B1; OPS-18 Deep Cleaning Request Post Move-out - Apt 506; OPS-17 Restroom Odor & Blocked Drain - Ground Floor.
- All created 22/Oct/26 by reporter Inamul Hasan.

Step 3 - Queue Review: After Assignment

All open queue - tickets assigned and progressing




Key details

- Same 20 work items, now assigned to Inamul Hasan with updated statuses.
- OPS-21: Open | OPS-20: Work in progress | OPS-19: Completed | OPS-18: Pending | OPS-17: Work in progress.

Step 4 - Work in Progress Update (OPS-20)

OPS-20: CCTV Camera #14 Blind Spot Realignment




Key details

- Status: Work in progress.
- Customer-visible comment: Technician adjusting camera lens and checking monitor feed.
- Internal note (yellow, lock icon): Security Tech adjusting camera angle to cover exit door.

Step 5 - Completion and Customer Reply (OPS-19)

OPS-19: Rodent Inspection Request - Garbage Room B1




Key details

- Status: Completed.
- Customer-visible comment: Inspection complete; 4 rodent bait stations installed.
- Internal note (yellow, lock icon): Pest team inspected garbage room B1 and placed bait boxes.

Step 6 - Completed Ticket Detail (OPS-2)

OPS-2: AC drainage issue - Completed




Key details

- Status: Completed. Assignee and Reporter: Inamul Hasan. Priority: Medium. Request type: Report a system problem.
- Customer-visible comment: AC drainage blockage cleared and tested. Cooling restored.
- Internal note (yellow, lock icon): Dispatched HVAC Senior Tech John for immediate inspection.

Step 7 - All Work Overview

All work - 20 of 20 items



Key details

- Shows Work, Assignee, Reporter, Priority and Status for each ticket. All visible items are assigned to Inamul Hasan with Medium priority.
- Statuses in view include Open, Work in progress, Completed, Pending, Resolved and In Progress.

Ticket Register (from screenshots)

Tickets visible in the All work view and queue screenshots. Reporter and assignee for all: Inamul Hasan. Priority: Medium.

Key	Summary	Status
OPS-21	Visitor Pass Printer Paper Jam - Reception Desk	Open
OPS-20	CCTV Camera #14 Blind Spot Realignment	Work in progress
OPS-19	Rodent Inspection Request - Garbage Room B1	Completed
OPS-18	Deep Cleaning Request Post Move-out - Apt 506	Pending
OPS-17	Restroom Odor & Blocked Drain - Ground Floor	Work in progress
OPS-16	Tenant Access Keycard Replacement Request	Completed
OPS-15	Irrigation Pipe Leakage in Garden - East Lawn	Pending
OPS-14	Overflowing Garbage Chute - Floor 12	Resolved
OPS-13	Pest Control Treatment Request - Apt 304	In Progress
OPS-12	Emergency Chemical Spill Cleaning - Loading Bay	Completed
OPS-11	Main Gate Access Barrier Sensor Faulty - Entrance	Completed
OPS-2	AC drainage blockage (cooling restored)	Completed