

NM-2024-19: Slip at CT-101 basin walkway during monsoon cleaning

Incident / Near-Miss Report: NM-2024-19 Category: near_miss_slip

Date: 2024-06-14 Area: Area 1 Equipment: CT-101

Title: Slip at CT-101 basin walkway during monsoon cleaning

NARRATIVE:

Contractor slipped on algae-slick walkway during basin cleaning; caught handrail, no injury.

ROOT CAUSE: Walkway anti-skid worn; monsoon algae growth.

PRECURSOR CONDITIONS: monsoon; basin cleaning task

CORRECTIVE ACTIONS: Anti-skid strips replaced.

Reported to: M. Pillai (Safety Officer)