

INSPECTION REPORT INSP-E201-2025-10-01

Inspection Report: INSP-E201-2025-10-01

Equipment / Location: E-201 Date: 2025-10-01

Method: thermal performance survey Result: PASS

DETAILS:

E-201 CW-side approach temperature 2.1 degC above clean baseline. Post-cleaning performance restored.

Inspector: N. Kaur (Inspection Engineer)