

INSPECTION REPORT INSP-STR101-2023-07-18

Inspection Report: INSP-STR101-2023-07-18

Equipment / Location: STR-101 Date: 2023-07-18

Method: dP gauge reading Result: ALERT

DETAILS:

STR-101 differential pressure recorded 0.92 bar (normal < 0.3, clean ~0.1). Basket blinding consistent with monsoon CW turbidity from CT-101 basin. Cleaning recommended within 48 h.

Inspector: N. Kaur (Inspection Engineer)