

Official Verification & Diagnostics Report



2026 suzuki s

gt

Verification Score

90/100



Unique Report ID

REP-881033

Certified Technician

alx

Inspection Date

May 21, 2026

Verification Package

Premium Service

This document is a certified inspection record protected by digital signature keys. Authenticity can be verified at any time.



01 / CLIENT & VEHICLE COMPREHENSIVE SPECIFICATIONS

1. CLIENT / AUDITEE INFORMATION

Customer Full Name	Location / City
sathish kumar	Dubai
Customer Email	Customer Phone
sathish@gmail.com	9566816369
Customer Address	
chennai	

2. DETAILED VEHICLE SPECIFICATION MATRIX

Vehicle Make	Vehicle Model
suzuki	s
Variant / Trim	Model Year
gt	2026
Fuel Type	Transmission Type
Petrol	Automatic
Chassis / VIN Number	Engine Number
wp	eng
Registration / License Number	Odometer Reading
k	150000
Insurance & Valuation Details	Associated Booking ID
axa	b



02 / GENERAL DIAGNOSTICS & SYSTEM ASSESSMENT

EXPERT DIAGNOSTIC VERDICT SUMMARY:

inspe

1. CRITICAL STRUCTURAL & SAFETY ATTENTION AREAS

Body & Structural State	✓ PASSED — No defects or issues reported.
Accidental History	✓ PASSED — No defects or issues reported.
Engine & Gearbox	✓ PASSED — No defects or issues reported.
Water Logged / Flood Check	✓ PASSED — No defects or issues reported.
OBD Scan Errors Details	■ ATTENTION REQUIRED — zero

2. TECHNICAL INSTRUMENT READOUTS

Paint Thickness Analyzer (Readings in µm)			OBD Diagnostic Computer Scanner	
Panel	Value	Status	OBD STATUS: CLEAN	
Hood	112 µm	Original	No active diagnostic trouble codes (DTCs) found. Engine management system reporting nominal values.	
Front Bumper	108 µm	Original		
Left Fender	115 µm	Original		
Right Fender	110 µm	Original		
Left Door	118 µm	Original		
Right Door	114 µm	Original		
Roof	105 µm	Original		
Rear Hatch	111 µm	Original		



03 / DETAILED MECHANICAL AUDIT (PART 1 - CATEGORIES 1 TO 7)

Drivetrain & Engine	
Engine oil level & quality Oil is fresh and at optimal fill level.	Normal
Coolant system hold pressure No leaks in radiator, hoses, or expansion tank.	Normal
Chassis & Underbody	
Frame rails & side members No structural damage or structural distortion detected.	Normal
Underbody shields & floor pans Covers are fully secure. Floor pans are intact.	Normal
Cabin & Interior Checks	
Seats & premium leather upholstery Upholstery is clean. Heating/cooling works perfectly.	Normal
Seatbelts & tension anchors Anchors engage tightly. Retractor inertia locks function securely.	Normal
Brake System	
Brake rotors & calipers Rotors show uniform wear without deep scoring.	Normal
Brake pads thickness Pad thickness is well above safety wear indicators.	Normal
Electricals & Battery	

Battery charge & cranking voltage Healthy cold cranking amps and stable open circuit voltage.	Normal
Alternator charging output Charging voltage remains optimal under full electrical load.	Normal

Steering & Suspension	
Steering rack & tie rods Steering feels direct and responsive. Boots are fully intact.	Normal
Shock absorbers & struts No fluid dampening leaks, coils show no fractures.	Normal

Tyres & Wheels	
Tread depth & wear pattern Uniform wear across all four tyres, healthy tread depth.	Normal
Alloy wheel rims structural safety No structural fractures, curb rashes, or bends detected.	Normal



04 / DETAILED MECHANICAL AUDIT (PART 2 - CATEGORIES 8 TO 13)

Exterior Body & Paint

Panel gaps alignment

Panel alignments conform to factory dimensional specs.

Normal

Cosmetic paint condition

Uniform paint thickness, no major swirl marks or scratches.

Normal

Safety Systems

SRS Airbags readiness

Airbag control module logs clean diagnostics with no fault codes.

Normal

ABS & Traction Control

Anti-lock brake actuators and wheel sensors are functional.

Normal

Air Conditioning & HVAC

Compressor engagement & cooling

Compressor cycles quietly, vent temperature drops quickly.

Normal

Cabin air filter & blower speed

Optimal air throughput across all fan speed profiles.

Normal

Lighting & Indicators

Headlights & high beams

LED clusters operate at full intensity and alignment.

Normal

Tail lights & indicators

Lenses are clear, indicators flash at normal frequency.

Normal

Transmission & Clutch

Gear engagement & synchro action Smooth shifts without gear clash or slip under throttle.	Normal
Torque converter or clutch fluid Fluid level and condition conform to standard specs.	Normal

Road Test & Performance	
Straight line tracking & stability Vehicle tracks straight, steering wheel is perfectly centered.	Normal
NVH (Noise, Vibration, Harshness) Cabin remains quiet, free of abnormal mechanical vibrations.	Normal

Inspector Executive remarks

EXECUTIVE EVALUATION NOTES:
"inte"

Official Quality Certification This report represents the professional evaluation of the inspecting technician using certified OBD systems and paint analyzer tools. The vehicle status reflects data captured on the date of inspection.	Certified Signature ✓ SECURE SIGNED alx
---	---

Verified Inspection Photo Gallery



Vehicle Angle #1



Vehicle Angle #2



Vehicle Angle #3



Vehicle Angle #4

◆ CERTIFIED ROLE-BASED MULTI-POINT VEHICLE VERIFICATION SYSTEM ◆

LEGAL DISCLAIMER: This is an official secure document compiled by AutoInspect Network.
To verify the digital integrity of this report online, visit autoinspect.ai/verify?id=REP-881033.