



## 2020 suzuki suzuki 2020

SUZUKI 2020

Verification Score

90/100



Unique Report ID

REP - 987715

Certified Technician

ALEX

Inspection Date

May 22, 2026

Verification Package

Premium Service



## 01 / CLIENT & VEHICLE COMPREHENSIVE SPECIFICATIONS

### 1. CLIENT / AUDITEE INFORMATION

|                    |                 |
|--------------------|-----------------|
| Customer Full Name | Location / City |
| mano mano          | Dubai           |
| Customer Email     | Customer Phone  |
| mano@gmail.com     | 9566816379      |
| Customer Address   |                 |
| chennai            |                 |

### 2. DETAILED VEHICLE SPECIFICATION MATRIX

|                      |                   |
|----------------------|-------------------|
| Vehicle Make         | Vehicle Model     |
| suzuki               | suzuki 2020       |
| Variant / Trim       | Model Year        |
| SUZUKI 2020          | 2020              |
| Fuel Type            | Transmission Type |
| Petrol               | Automatic         |
| Chassis / VIN Number | Engine Number     |
| WPOZEEZ              | ENG-638012        |

Registration / License Number

TN 23 AE 2002

Odometer Reading

15000km

Insurance & Valuation Details

AXA comprehensive

Associated Booking ID

B-5432



02 / GENERAL DIAGNOSTICS & SYSTEM ASSESSMENT

EXPERT DIAGNOSTIC VERDICT SUMMARY:

Inspected

1. CRITICAL STRUCTURAL & SAFETY ATTENTION AREAS

Body & Structural State

✓ PASSED — No defects or issues reported.

Accidental History

✓ PASSED — No defects or issues reported.

Engine & Gearbox

■ ATTENTION REQUIRED — no active

Water Logged / Flood Check

✓ PASSED — No defects or issues reported.

OBD Scan Errors Details

■ ATTENTION REQUIRED — zero logged

2. TECHNICAL INSTRUMENT READOUTS

Paint Thickness Analyzer (Readings in µm)

| Panel        | Value  | Status   |
|--------------|--------|----------|
| Hood         | 112 µm | Original |
| Front Bumper | 108 µm | Original |
| Left Fender  | 115 µm | Original |
| Right Fender | 110 µm | Original |
| Left Door    | 118 µm | Original |
| Right Door   | 114 µm | Original |
| Roof         | 105 µm | Original |
| Rear Hatch   | 111 µm | Original |

OBD Diagnostic Computer Scanner

OBD STATUS: CLEAN

No active diagnostic trouble codes (DTCs) found. Engine management system reporting nominal values.



## 03 / DETAILED MECHANICAL AUDIT (PART 1 - CATEGORIES 1 TO 7)

### Drivetrain & Engine

#### Engine oil level & quality

Normal

Oil is fresh and at optimal fill level.

#### Coolant system hold pressure

Normal

No leaks in radiator, hoses, or expansion tank.

### Chassis & Underbody

#### Frame rails & side members

Normal

No structural damage or structural distortion detected.

#### Underbody shields & floor pans

Normal

Covers are fully secure. Floor pans are intact.

### Cabin & Interior Checks

#### Seats & premium leather upholstery

Normal

Upholstery is clean. Heating/cooling works perfectly.

#### Seatbelts & tension anchors

Normal

Anchors engage tightly. Retractor inertia locks function securely.

### Brake System

#### Brake rotors & calipers

Normal

Rotors show uniform wear without deep scoring.

### Brake pads thickness

Normal

Pad thickness is well above safety wear indicators.

## Electricals & Battery

### Battery charge & cranking voltage

Normal

Healthy cold cranking amps and stable open circuit voltage.

### Alternator charging output

Normal

Charging voltage remains optimal under full electrical load.

## Steering & Suspension

### Steering rack & tie rods

Normal

Steering feels direct and responsive. Boots are fully intact.

### Shock absorbers & struts

Normal

No fluid dampening leaks, coils show no fractures.

## Tyres & Wheels

### Tread depth & wear pattern

Normal

Uniform wear across all four tyres, healthy tread depth.

### Alloy wheel rims structural safety

Normal

No structural fractures, curb rashes, or bends detected.



## 04 / DETAILED MECHANICAL AUDIT (PART 2 - CATEGORIES 8 TO 13)

### Exterior Body & Paint

#### Panel gaps alignment

Normal

Panel alignments conform to factory dimensional specs.

#### Cosmetic paint condition

Normal

Uniform paint thickness, no major swirl marks or scratches.

### Safety Systems

#### SRS Airbags readiness

Normal

Airbag control module logs clean diagnostics with no fault codes.

#### ABS & Traction Control

Normal

Anti-lock brake actuators and wheel sensors are functional.

### Air Conditioning & HVAC

#### Compressor engagement & cooling

Normal

Compressor cycles quietly, vent temperature drops quickly.

#### Cabin air filter & blower speed

Normal

Optimal air throughput across all fan speed profiles.

### Lighting & Indicators

#### Headlights & high beams

Normal

LED clusters operate at full intensity and alignment.

Tail lights & indicators

Normal

Lenses are clear, indicators flash at normal frequency.

Transmission & Clutch

Gear engagement & synchro action

Normal

Smooth shifts without gear clash or slip under throttle.

Torque converter or clutch fluid

Normal

Fluid level and condition conform to standard specs.

Road Test & Performance

Straight line tracking & stability

Normal

Vehicle tracks straight, steering wheel is perfectly centered.

NVH (Noise, Vibration, Harshness)

Normal

Cabin remains quiet, free of abnormal mechanical vibrations.

Inspector Executive remarks

EXECUTIVE EVALUATION NOTES:

"Additional"

Official Quality Certification

This report represents the professional evaluation of the inspecting technician using certified OBD systems and paint analyzer tools. The vehicle status reflects data captured on the date of inspection.

Certified Signature

✓ SECURE SIGNED

ALEX

Verified Inspection Photo Gallery



Vehicle Angle #1



Vehicle Angle #2



Vehicle Angle #3



Vehicle Angle #4

---

◆ CERTIFIED ROLE-BASED MULTI-POINT VEHICLE VERIFICATION SYSTEM ◆

**LEGAL DISCLAIMER:** This is an official secure document compiled by AutoInspect Network.  
To verify the digital integrity of this report online, visit [autoinspect.ai/verify?id=REP-987715](https://autoinspect.ai/verify?id=REP-987715).