

❖ AUTOINSPECT GUARDIAN PRO

CERTIFIED ROLE-BASED MULTI-POINT VEHICLE VERIFICATION SYSTEM

2022 AUDI AUDI 22

Not Specified

Verification Score

90/100



Unique Report ID

REP - 151756

Certified Technician

AutoInspect Certified Expert

Inspection Date

May 20, 2026

Verification Package

Premium Service

01 / CLIENT & VEHICLE COMPREHENSIVE SPECIFICATIONS

1. CLIENT / AUDITEE INFORMATION

Customer Full Name surya	Location / City Dubai
Customer Email surya@gmail.com	Customer Phone Not Registered
Customer Address Not Specified	

2. DETAILED VEHICLE SPECIFICATION MATRIX

Vehicle Make AUDI	Vehicle Model AUDI 22
Variant / Trim Not Specified	Model Year 2022
Fuel Type Petrol	Transmission Type Automatic
Chassis / VIN Number wpozz92	Engine Number Not Specified
Registration / License Number k-3333	Odometer Reading 14000km
Insurance & Valuation Details Not Specified	Associated Booking ID Not Specified

02 / GENERAL DIAGNOSTICS & SYSTEM ASSESSMENT

EXPERT DIAGNOSTIC VERDICT SUMMARY:

inspected

1. CRITICAL STRUCTURAL & SAFETY ATTENTION AREAS

Body & Structural State	✓ PASSED — No defects or issues reported.
Accidental History	✓ PASSED — No defects or issues reported.
Engine & Gearbox	■ ATTENTION REQUIRED — no active
Water Logged / Flood Check	✓ PASSED — No defects or issues reported.
OBD Scan Errors Details	■ ATTENTION REQUIRED — zero

2. TECHNICAL INSTRUMENT READOUTS

Paint Thickness Analyzer (Readings in µm)			OBD Diagnostic Computer Scanner	
Panel	Value	Status	OBD STATUS: CLEAN	
Hood	112 µm	Original	No active diagnostic trouble codes (DTCs) found. Engine management system reporting nominal values.	
Front Bumper	108 µm	Original		
Left Fender	115 µm	Original		
Right Fender	110 µm	Original		
Left Door	118 µm	Original		
Right Door	114 µm	Original		
Roof	105 µm	Original		
Rear Hatch	111 µm	Original		

03 / DETAILED MECHANICAL AUDIT (PART 1 - CATEGORIES 1 TO 7)

Drivetrain & Engine	
Engine oil level & quality Oil is fresh and at optimal fill level. No metallic deposits.	Pass
Coolant system hold pressure No leaks in radiator, hoses, or expansion tank.	Pass
Transmission shifts Lightning fast shifts, clutch pressure parameters are within OEM specs.	Pass
Chassis & Underbody	
Suspension control arms Bushings and ball joints are tight with no dry rot.	Pass
Brake rotors & carbon ceramic discs Friction surface is perfectly flat. Brakes at high capacity.	Pass
Cabin & Interior Checks	
Seats & premium leather upholstery Upholstery is clean, with minimal bolster wear. Heating/cooling works perfectly.	Pass
Seatbelts, buckles & tension anchors Anchors engage tightly. Retractor inertia locks function securely.	Pass
Steering column & adjustment control Power telescope and tilt operate smoothly. Steering grip leather is pristine.	Pass
Console trim, dashboard & storage Glove compartment, cup holders, and armrests are solid and scratch-free.	Pass

04 / DETAILED MECHANICAL AUDIT (PART 2 - CATEGORIES 8 TO 13)

All primary check categories represented in Part 1.

Verified Inspection Photo Gallery



Vehicle Angle #1

Inspector Executive remarks

EXECUTIVE EVALUATION NOTES:
"additional"

Official Quality Certification This report represents the professional evaluation of the inspecting technician using certified OBD systems and paint analyzer tools. The vehicle status reflects data captured on the date of inspection.	Certified Signature ✓ SECURE SIGNED AutoInspect Certified Expert
---	---