



01 / VEHICLE DIAGNOSTICS & SYSTEM ASSESSMENT OVERVIEW

1. VEHICLE DETAILS

Customer Name	ramesh raja	Inspection Date	May 27, 2026
Car Make	Suzuki	Car Model	Suzuki 2020
Car Registration Number	TN 23 Ak 1234	VIN Number	WOPOZHIANF
Odometer Reading	122434	Fuel Type	Petrol
Transmission	Automatic	Location Manual	TAMBARAM

2. OVERALL SUMMARY VEHICLE

EXPERT DIAGNOSTIC VERDICT SUMMARY:

3. ATTENTION NEEDED AREAS

Body & Structural State	✓ PASSED — System reporting nominal status with no active anomalies.
Accidental History	✓ PASSED — System reporting nominal status with no active anomalies.
Engine & Gearbox Performance	■ ATTENTION REQUIRED — NO ACTIVE
OBD Scan Errors (DTC)	■ ATTENTION REQUIRED — ZERO
Water Logged (Flooded)	■ ATTENTION REQUIRED — NO LOGGED
OBD Scan Report	✓ PASSED — System reporting nominal status with no active anomalies.
OBD Pre-scan Report	✓ PASSED — System reporting nominal status with no active anomalies.
Background History Check	✓ PASSED — System reporting nominal status with no active anomalies.
Blacklist Status	✓ CLEAN — System reporting nominal status with no active anomalies.

02 / DETAILED CHECKPOINTS (PART 1: ENGINE & EXTERIOR)

ENGINE CABIN AUDIT

Check Item	Status
Engine Physical Condition <i>No external leaks, cracked mounts, or abnormal component wear.</i> 	Major Repaired
Engine Oil Condition <i>Oil level is optimal, viscosity and color are within healthy specs.</i>	Dirty
Coolant <i>Coolant level is correct, no signs of contamination or radiator leaks.</i>	Leaking
Battery Condition <i>Voltage output is stable, terminals are clean and corrosion-free.</i>	Weak

Fuel Injector <i>No leakage or abnormal noise, fuel delivery is stable.</i>	Damaged
Left Apron <i>Structural apron is intact with no weld marks or repair signs.</i>	Replaced
Left Apron Leg <i>Apron extension leg is straight, showing no structural damage.</i>	Need Attention
Right Apron <i>Structural apron is intact with no weld marks or repair signs.</i>	Replaced
Right Apron Leg <i>Apron extension leg is straight, showing no structural damage.</i>	Warning
Upper Cross Member <i>Upper core support is original and properly aligned.</i>	Warning
Normal Lower Cross Member <i>Lower radiator crossmember is undamaged with no denting.</i>	Damaged
Normal Radiator and Support <i>Radiator core and fan shroud are secure and undamaged.</i>	Need Attention

Radiator Fan Fan shroud is intact, blades rotate freely without wobble.	Warning
Firewall Insulation and structural sheet metal are in factory condition.	Normal
Engine Oil Sump Sump pan is clean with no damage, dents, or active leaks.	Normal

Engine Cabin Reference Images:



EXTERIOR AND BODY AUDIT

Check Item	Status
Cowltop Plastic cowl trim is secure and free of weathering or cracks.	Need Attention
Windshield Laminated glass has no chips, bullseyes, or structural cracks.	Chipped

Bonnet <i>Engine hood panel is straight with uniform shut lines.</i>	Repainted
Front Bumper <i>Securely mounted, paint finish is smooth with no major scuffs.</i>	Cracked
Front Bumper Grill <i>Grille mesh is fully intact, all clips and tabs secure.</i>	Dented
Headlight Left <i>Lens is clear, housing is sealed, and LED/HID elements function.</i>	Cracked/Broken
Headlight Right <i>Lens is clear, housing is sealed, and LED/HID elements function.</i>	Normal
Fog Lamp Left <i>Lower fog lamp is clear and operates at full brightness.</i>	Normal
Fog Lamp Right <i>Lower fog lamp is clear and operates at full brightness.</i>	Normal
Normal Fender Left <i>Left fender panel matches factory paint and alignment specifications.</i>	Normal

Mirror Assembly Left <i>Power adjust, fold, and indicator repeater function smoothly.</i>	Normal
A Pillar Left <i>Structural A-pillar is straight with original factory spot welds.</i>	Normal
B Pillar Left <i>Structural B-pillar has no deformation or repair history.</i>	Normal
C Pillar Left <i>Structural C-pillar is in excellent original condition.</i>	Normal
Left Door Front <i>Hinges operate smoothly, door panel alignment is straight.</i>	Normal
Left Door Rear <i>Rear door shut line is uniform, seals are fully intact.</i>	Normal
Running Board Left <i>Sill panel is straight, no rust or underbody impact damage.</i>	Normal
Quarter Panel Left <i>Left rear quarter is smooth with original factory contours.</i>	Normal

Roof Outer Roof panel is clean, no hail damage or paint blemishes.	Normal
--	-------------------



03 / DETAILED CHECKPOINTS (PART 2: INTERIOR & TEST DRIVE)

INTERIOR AUDIT

Check Item	Status
Rear Windshield <i>Rear glass heating element grid is functional and intact.</i>	Normal
Boot Door (Dicky) <i>Trunk lid lifts smoothly on dampers, latch locks securely.</i>	Normal
Rear Bumper <i>Bumper cover is perfectly aligned, parking sensors secure.</i>	Normal
Boot Floor <i>Spare tire well floor pan is straight and free of moisture.</i>	Normal
Tool Kit <i>Jack, wheel wrench, and tow hook are present and complete.</i>	Normal

Tail Lamp Left <i>Left rear light assembly operates cleanly without moisture.</i>	Normal
Tail Lamp Right <i>Right rear light assembly operates cleanly without moisture.</i>	Normal
Quarter Panel Right <i>Right rear quarter has no denting or prior repair signs.</i>	Normal
Running Board Right <i>Right sill panel is undamaged and structurally sound.</i>	Normal
Right Door Rear <i>Right rear door opens and closes with solid seal pressure.</i>	Normal
Right Door Front <i>Right front door glass and locks operate at full speed.</i>	Normal
A Pillar Right <i>Right A-pillar shows no repair signs or structural issues.</i>	Normal
B Pillar Right <i>Right B-pillar structure is original and completely straight.</i>	Normal

C Pillar Right <i>Right C-pillar is free of repair, welds, or paint issues.</i>	Normal
Mirror Assembly Right <i>Right power mirror functions normally, mirror glass is clear.</i>	Normal
Fender Right <i>Right front fender has uniform gaps and original finish.</i>	Normal
Power Window <i>All windows raise and lower smoothly across full travel.</i>	Not Working
normal Power Window Remarks <i>Anti-pinch feature and master switch operates correctly.</i>	Slow Operation
ORVM Switch <i>Outer Rear View Mirror control pad is responsive.</i>	Need Attention

TEST DRIVE AUDIT

Check Item	Status
Airbags <i>SRS system reports no active diagnostic fault codes.</i>	Normal

airbags Instrument <i>Airbag warning indicator light illuminates and self-extinguishes.</i>	Normal
Cluster Visual check <i>Instrument panel displays clearly with no dead pixels.</i>	Normal
Music System Visual check <i>Infotainment display screen and control knobs operate cleanly.</i>	Normal
Music System Remarks <i>Audio output is balanced across all premium cabin speakers.</i>	Normal
Horn Working <i>Dual-tone horn sounds clear and triggers immediately.</i>	Normal
Wipers Working <i>Wiper motors, washer jets, and rain sensors function.</i>	Normal
All Exterior Lamps Working <i>High beams, low beams, and indicators function correctly.</i>	Normal
Interior Seat Condition All seats <i>Seat upholstery is clean, tracks adjust and lock securely.</i>	Normal

Sunroof <i>Glass sunroof slides and tilts quietly with no water leaks.</i>	Normal
Steering Wheel Mount Buttons <i>All steering wheel integrated audio and cruise buttons work.</i>	Normal
Rear Defogger Normal Reverse Camera and Sensor <i>Parking camera is clear, static/dynamic guide lines work.</i>	Normal
Airconditioner System 5°C - 8°C (Excellent) <i>AC compressor functions perfectly, cooling vent temperature is excellent.</i>	Normal
Clutch Normal Brakes <i>Brake pedal feel is firm, clutch engagement point is normal.</i>	Normal
Anti-lock Braking System (ABS) <i>ABS actuator responds correctly under sudden deceleration.</i>	Normal
Acceleration <i>Linear power delivery under throttle, no engine lag.</i>	Normal
Handbrake <i>Parking brake lever/electronic brake holds vehicle on incline.</i>	Normal

Gear Shifting <i>Transmission shifts cleanly across all ratios with no slippage.</i>	Normal
Gear Box Paddle Shifters <i>Steering wheel paddles shift gears instantly when toggled.</i>	Normal
Suspension <i>No abnormal squeaks or knocking over bumps, dampers are firm.</i>	Normal
Engine Sound and Vibration <i>Idle is steady, engine runs smoothly with no harsh vibration.</i>	Normal
Turbo <i>Turbocharger builds boost smoothly, no smoke or whistle.</i>	Normal
Pickup and Performance <i>Excellent throttle response and overall acceleration profile.</i>	Normal
General Noise <i>Cabin NVH levels are excellent, no wind or tire noise.</i>	Normal
All Wheel Bearing <i>Wheel hubs rotate quietly with no humming or play.</i>	Normal

Back Compression <i>No excessive crankcase pressure or blow-by from oil cap.</i>	Normal
Exhaust Pipe and Smoke <i>Clean exhaust output, no blue or white smoke under load.</i>	Normal
Flood Effectuated / Water Logged <i>No water silt, rust, or odor in footwells or seat brackets.</i>	Normal

04 / COMPRESSION EVIDENCE & GALLERY PHOTO MATRIX

Compression Check Video

CERTIFIED DYNAMIC EVIDENCE RECORD:

Click below to view the diagnostic engine sound and compression verification video:

<https://www.youtube.com/watch?v=-SAB0AcZgp4>

OBD Report (QR)



Other References



Inspection Gallery



Vehicle Angle #1



Vehicle Angle #2



Vehicle Angle #3



Vehicle Angle #4

INSPECTION EXPERT REMARKS:

- ONE
- TWO
- THREE

Official Quality Certification

This report represents the professional evaluation of the inspecting technician using certified OBD systems and diagnostic tools. The vehicle status reflects data captured on the date of inspection.

Certified Signature

✓ SECURE SIGNED

VICKY

LEGAL DISCLAIMER: This is an official secure document compiled by AutoInspect Network.
To verify the digital integrity of this report online, visit **autoinspect.ai/verify?id=REP-625704**.

powered by zenelait infotech