



RED BANNER ALERT

mainroads
WESTERN AUSTRALIA

SHW Serious Incident (SI) – Preliminary Notice

Date of Incident	12 May 2026	Time of Incident	8:45 AM
Directorate / Region	RMO – Kimberley Region	Main Roads or Contractor	Contractor
iSafe Event Type	Procedure Breach	iSafe Incident Number	INC-0127
Actual Consequence	Moderate	Potential Consequence	Major

Incident Short Description	Contractor observed transporting personnel on a forklift with elevated tines.
-----------------------------------	---

What Happened

At approximately 8:45 AM, it was observed that a contracted forklift operator and truck driver were unloading a truck at the project camp accommodation. During this activity, the forklift operator was seen transporting the truck driver with the forklift with elevated tines, and whilst they were standing on a pallet supported by a trolley jack.

The SHW Coordinator stopped the travel and spoke to the operator, who was also observed not wearing a seatbelt. SHW advised a serious procedure breach and non-compliant operation of a forklift and contact the Project Manager and Camp Manager.

Following the incident, the forklift operator provided a statement indicating that they recognised that not wearing a seatbelt was unsafe; however, they did not perceive transporting the truck driver on a pallet as being of the same level of risk.

Post-incident AOD testing was conducted, with the forklift operator returning negative results. It has been determined that the forklift operator will be stood down from site, pending the outcome of an investigation.



A formal ICAM investigation has commenced. Once completed, the lessons learnt will be communicated / shared through a final Grey Banner Alert as soon as practicable.



This serious potential incident aligns with the Main Roads Critical Risk profile relating to
Mobile Plant

Distribution of Notice

Main Roads Personnel and Contracting Organisations