



RED BANNER ALERT

mainroads
WESTERN AUSTRALIA

SHW Serious Incident (SI) – Preliminary Notice

Date of Incident	30 th June 2026	Time of Incident	9:40 AM
Directorate / Region	RMO – Kimberley Region	Main Roads or Contractor	Contractor
isafe Event Type	Damage / Loss	isafe Incident Number	INC-0368
Actual Consequence	Moderate	Potential Consequence	Major

Incident Short Description	Loader rolled over whilst undertaking operations in the materials pit
-----------------------------------	---

What Happened

At approximately 9:40 AM, a loader operator was working within the materials pit and had filled the loader bucket with material. While reversing away from the gravel stockpile, a large rock fell from the bucket and came to rest on the ground behind the machine.

The operator then proceeded to stockpile the material. During this activity, the loader travelled over the rock that had fallen from the bucket. As a result, the loader became unstable, tilted, and slowly rolled onto its right-hand side while the bucket remained fully loaded. The operator was able to safely exit the loader and did not sustain any injuries because of the incident.

Following the incident, the area was immediately isolated and made safe. Work in the vicinity has been suspended while an investigation is undertaken to determine whether there have been any spills or damage to the loader. The loader will remain in its current position until it has been assessed, and a safe recovery plan has been developed.



A formal ICAM investigation has commenced. Once completed, the lessons learnt will be communicated/shared through a final Grey Banner Alert as soon as practicable.



This serious potential incident aligns with the Main Roads Critical Risk profile relating to
Mobile Plant

Distribution of Notice

Main Roads Personnel and Contracting Organisations