



RED BANNER ALERT

mainroads
WESTERN AUSTRALIA

SHW Serious Incident (SI) – Preliminary Notice

Date of Incident	8 March 2024	Time of Incident	10:30
Directorate / Region	RMO – MWG	Main Roads or Contractor	Main Roads
EQSafe Event Type	SHW Procedural Breach	EQSafe Incident Number	38716
Actual Consequence	Minor	Potential Consequence	Major

Incident Short Description	New Plant to Site - Breach of Onboarding Procedure
-----------------------------------	--

What Happened

After a visual inspection of a flat top trailer, it was identified that there were several operational breaches concerning the use of the equipment as follows:

- Trailer overloaded.
- No electric brakes or break-away system on the trailer.
- Trailer not correctly hitched.
- No operational prestart check available for the trailer or the vehicle towing it at the time of the inspection; and
- No Risk assessment or onboarding check conducted on trailer prior to use.

The trailer had been used for transporting equipment on the network between the dates from 26 Feb – 6 March 2024. At the time of inspection, the team were away on their rostered break.





This serious potential incident aligns with the Main Roads Critical Risk profile relating to
Vehicles and Driving

Distribution of Notice

Main Roads Personnel and Contracting Organisations