



RED BANNER ALERT



mainroads
WESTERN AUSTRALIA

SHW Serious Incident (SI) – Preliminary Notice

Date of Incident	12 June 2024	Time of Incident	11:30 pm
Directorate / Region	IDD / Metropolitan	Main Roads or Contractor	Contractor
EQSafe Event Type	Injury / Illness	EQSafe Incident Number	41154
Actual Consequence	Moderate	Potential Consequence	Moderate

Incident Short Description	Plant operator finger pinched between multi-wheel roller tyre and scrapper.
-----------------------------------	---

What Happened

An asphalt contractor operator (Injured Person – IP) was undertaking a pre-start inspection on a multi-wheel roller at start of the shift. It was identified that a rear scraper required to be repositioned. Unable to un-jam and move the scraper using the machine lever, the operator requested assistance from another worker.

During the process, the operator's finger was placed between the scraper and the tyre. At the same time the second worker forced the scraper back into position. The impact resulted in a crush injury to the operator's right middle fingertip.



Injured Persons hand position

A formal investigation has commenced. Once completed, the lessons learnt will be communicated/shared through a final Grey Banner Alert as soon as practicable.

Distribution of Notice	Main Roads Personnel and Contracting Organisations
-------------------------------	--