



GREY BANNER ALERT



SHW Serious Incident (SI) – Final Notice

Date of Incident:	15 February 2023	Time of Incident:	12:20 pm
Region / Directorate:	IDD	Main Roads or Contractor:	Contractor
EQSafe Event Type:	Damage/Loss	EQSafe Incident Number:	30028
Actual Consequence:	Moderate	Potential Consequence:	Major

Incident Short Description:	Moxy Slipped down embankment
------------------------------------	------------------------------

Executive Summary:

On 15/2/2023 a Moxy was hauling dirt , all conditions were normal and part of everyday work activities. Standard radio communications were followed as in no requirement for call up for Moxys to pass when travelling in opposite direction when using a 15mtr wide haul road.

At approximately 10:00hrs, a Moxy was travelling at approximately 20kmph on Moxy track, when an oncoming Scraper and another Moxy was heading in the opposite direction, the operator moved over to let them pass when the rear right tyre set slipped down the side of the 2/1 embankment, causing the rear tray to roll onto its side.

Work was immediately stopped, and supervisor was informed.

HSE was notified, and investigation was started.

Incident Photos:



Moxy position following incident



Moxy position following incident



Moxy position following incident

Contributing Factors:

- Operator travelling too close to edge on 15m profile, lack of concentration.
- Operator unaware of soft and un-compacted edges
- SWMS didn't capture Hazards in driving too close to edges.

Corrective Actions:

- Install delineator along Moxy track to define uncompacted edges
- SWMS review to capture working close to soft edges
- Incident findings to be relayed to all work crew



Critical Risk:

This serious potential incident aligns with the Main Roads Critical Risk Profile relating to **Mobile Plant.**

Distribution of Notice:

Main Roads Personnel and Contracting Organisations