



GREY BANNER ALERT



SHW Serious Incident (SI) – Final Notice

Date of Incident:	12/05/2022	Time of Incident:	15.00
Region / Directorate:	Kimberley	Main Roads or Contractor:	Contractor
EQSafe Event Type:	Near Miss	EQSafe Incident Number:	31371
Actual Consequence:	Insignificant	Potential Consequence:	Major

Incident Short Description:	Operator riding in Excavator bucket.
------------------------------------	--------------------------------------

Executive Summary:

A 36-tonne excavator and Bulldozer were utilised to construct the low-level crossing, five pipes were installed, and the crossing was connected to the other side.

The dozer operator exited the machine to check the newly constructed site. The rock embankment began to dam water and cause overflowing over the crossing. While the dozer operator was on site, the quantity of water over the crossing increased to approximately 20 to 30mm.

The dozer operator requested a ride back to the dozer in the excavator bucket to avoid getting wet boots.

An anonymous source took a photo of the dozer operator riding in the excavator bucket and sent it to the Project Manager.



Contributing Factors:	
• Operator didn't want to get his boots wet. • Excavator operator agreed to transport the dozer operator. • Both plant operators acknowledged they understood this practice should not be performed.	
Corrective Actions:	
• The Site Supervisor spoke to the operators and the operators' employer. • The Supervisor told all parties that a future safety breach will lead to instant dismissal. • Notify contractor immediately and discuss the violation to prevent reoccurrence. Implement (documented) disciplinary action with both Operators. • Communicate the potential dangers associated with riding on mobile plant at the Pre-Start Meeting. This serious potential incident aligns with the Main Roads Critical Risk profile relating to: Mobile Plant 	

Distribution of Notice:	Main Roads Personnel and Contracting Organisations
--------------------------------	--