



RED BANNER ALERT

mainroads
WESTERN AUSTRALIA

SHW Serious Incident (SI) – Preliminary Notice

Date of Incident	1 December 2023	Time of Incident	1500
Directorate / Region	Goldfields / Esperance	Main Roads or Contractor	Employee
EQSafe Event Type	SHW Incident – Injury	EQSafe Incident Number	35888
Actual Consequence	Moderate	Potential Consequence	Major

Incident Short Description	IP sustained crush and nail bed injury to LH index finger whilst using Auto Compaction Machine
-----------------------------------	--

What Happened

On Friday, 1 December 2023, at 1500, a Materials Technician (IP) was using an Automatic Compactor Machine in the Laboratory. The Machine was making an unusual noise, and the IP asked the Trainee to stop it so they could investigate.

The IP has opened the front cover and was investigating what was causing the unusual noise when the metal block inside the unit dropped and crushed the left index finger damaging their nail bed.

The IP was taken to the Regional Hospital who advised surgery was required. The IP was flown to Perth, where they underwent surgery the following morning.

The machine was tagged out to prevent further use.

A formal ICAM investigation has commenced. Once completed, the lessons learnt will be communicated/shared through a final Grey Banner Alert as soon as practicable.




Photo of Compaction Machine

A formal ICAM investigation has commenced. Once completed, the lessons learnt will be communicated/shared through a final Grey Banner Alert as soon as practicable.

Distribution of Notice	Main Roads Personnel and Contracting Organisations
-------------------------------	--