Order List

Order ID	Repair Item(s)	Name	Phone	Appt. Date/Ti me	Order Date	Estima te Cost(\$)	Contra ctor Cost(\$)	Commi sion(\$)
TP511 40602	Samsu ng Note 8 - SM-95 0 iPhone X Repair Option s: Back Glass Replac ement What color is your iPhone X?: Gold	Himan su Panch al Himan su Panch al	91942 68931 50	11/09/ 2018 12:00 pm	11/06/ 2018 04:43 AM	599	1000	-401
TP405 24911	LG G2 Repair iPhone X Repair Option s: Front Display Screen Replac ement What color is your iPhone X?: Gold	Himan su Panch al Himan su Panch al	91942 68931 50	11/08/ 2018 11:00 am	11/06/ 2018 04:41 AM	499		