

Site Safety Tour — Report

Generated 23/09/2025 18:40 (UK) — Score 94.87%

Details

Date	23/09/2025 07:26
Site / Area	Rochdale Road / Block 1
Lead / Participants	chris irlam / chris Irlam
Status	Open

Questions

Ref	Question	Result	Priority	Notes
1.1	Is the Site perimeter in place with Temporary	PASS	Low	
	works applied for Fixed or Hera's fencing, and are			
	gates secured with lockable devices.			
1.2	Has Safe access and egress been provided for	PASS	Medium	
	pedestrians and segregation applied away from			
	plant, equipment and materials.			
1.3	Is statutory signage for awareness, e.g., speed	PASS	_	
	limits, crossing points, and emergency locations in			
	place.			
1.4	Have designated storage areas away from	PASS	_	
	pedestrians been provided and barriered off.			
2.1	Are the statutory notice boards being displayed for	PASS	_	
	the McGoff Construction Ltd (H&S Policy &			
	Arrangements, F10, CPP, First Aid, Fire			
	information and Permits issued).			
2.2	Has the Construction Phase Plan been reviewed	PASS	_	
	for changes onsite.			
2.3	Have the site files been developed and contain the	PASS	_	
	required information under the correct appendixes.			
2.4	Has a Temporary works file been developed (Site	PASS	_	
	fencing, scaffold, propping, formwork, falsework,			
	structural supports etc) with training in place for the			
	appointed person.			
2.5	Have site inductions been completed, competency	PASS	_	
	details verified and PPE checked prior to			
	commencing work.			
2.6	Are first aiders and fire marshals trained,	PASS	_	
	certificates displayed and provisions suitable e.g.,			
	First aid equipment / defibrillator charged.			
2.7	Is the accident book in place and investigation	PASS		
	procedure briefed and understood in the event of			
	an incident onsite.			

3.1	Is the lighting in place which is suitable & sufficient
	internally and externally and task light for specific
	operations being used.

/IPROVEMEN	_	test notes for
		evidence



	O Validate Office Control of the Con			
3.2	Are access routes defined and clear of work	PASS	_	
	materials where required e.g., general walkways			
	and fire routes.			
3.3	Are emergency escape routes clear with fire	PASS	_	
	fighting equipment accessible and in service date.			
3.4	Are temporary electrical units in place with cables	PASS	_	
	elevated to eliminate potential slip, trip and falling			I
	hazards.			
3.5	Is housekeeping being managed for waste	PASS	_	
	materials, and provisions in place to remove waste			
	streams keeping work areas clear to eliminate			
	potential slip, trip and falling hazards.			
3.6	Are dust levels being managed onsite with suitable	PASS	_	
	equipment in place, e.g., medium rated extraction,			
	suppression systems, RPE etc.			
3.7	Are COSHH assessments in place and designated	PASS	_	
	storage areas for chemicals provided, with			
	ventilation suitable & sufficient being provided with			
	the correct PPE being used.			
4.1	Is Plant certification with reference to LOLER	N/A	_	
	(rotating plant & equipment, passenger/goods			
	hoist, MEWP etc) in place with competency levels			
	retained for site compliance.			
4.2	Has the hierarchy for WAH equipment been	PASS	_	
	considered, and equipment being used built to			
	manufacturers' instructions.			
4.3	Are scaffold designs in place, with statutory	PASS	_	
	inspections completed weekly and after adverse			
	weather conditions with corrective measures			
	required applied in line with relevant standards.			
4.4	Are scaffold lifts clear from materials and being	PASS	_	
	cleared daily to eliminate potential falling objects.			
5.1	Temporary Works	PASS	_	
5.2	Asbestos Management	PASS	_	
5.3	Lifting Operations	PASS		
5.4	Excavations	IPROVEMEN	_	more test notes
				and avidance

and evidence

testing
text



5.5	Confined Spaces	PASS		
6.1	Are site specific permits being issued and closed	PASS	_	
	out in line with site procedures.			
7.1	Occupational Health	PASS	_	
7.2	COVID-19 Management	PASS	_	
7.3	Biological Hazards & Considerations	PASS	_	
8.1	Has there been a requirement to conduct a safety	PASS	_	
	intervention at the time of the inspection.			
8.2	Is there a record of any site meetings where H&S	PASS	_	
	areas have been discussed with action plans set.			
8.3	Have any toolbox talks been delivered in the	PASS	_	
	calendar month.			
8.4	Have any accidents or incidents occurred in the	PASS	_	
	calendar month.			
9.1	Has an aspects and impacts assessment been	PASS	_	
	completed.			
9.2	Has there been an ecology report completed.	PASS	_	
9.3	Is there a facility to store fuel & hazardous	PASS	_	
	substances onsite.			
9.4	Have pollution and prevention controls onsite been	PASS		
	provided.			
10.1	Have waste licences and permits been obtained.	PASS		

Signature

