FACILITIES UPDATE

ALTAMESA & MCCART FSU (02810)

ACCOMPLISHED

Outside
- Parking lot lights
- Delineator extended to stop sign
- Remove owl off roof
- Landscaping (vendor starting Dec 7)
- Pressure wash awnings (scheduled recurring, twice monthly)
- Building lights
- Dumpster hole in wall
- Drainage hole in concrete (in front of cage)

Dining Room
- Bug light (Ecolab switch effective Dec 1)
- Front entrance door lock/hinge
- Back entrance door lock
- Fruit flies on exit sign/walls
- Adjust back door hydraulics
- Booth seat cover replacement (on order)

Front Counter / DT
- All gaskets
- KPS screen for mobile
- Outlets
- Sink not usable (being removed with refresh)
- Dessert lowboy
- Sauce wall secured
- Cover above chutes replaced
- Vent covers replaced
- DT drink tower leak (Coke contacted)
- Seal drink towers (materials purchased)
- Panic button in DT
- Air curtain

Playland
- Entire area deep cleaned
- Lock

Restrooms
- Women's single-stall door squeak
- Toilet repaired

Back Area
- Cage / closet cleanliness
- Cage pest prevention (walls)
- Emergency light secured
- Drain jetting completed

Kitchen
- All gaskets
- Thaw cabinet PM
- Thaw cabinets cleaned
- Freezer heat strip
- Vents cleaned
- Hobart replacement in progress
- Clean Henny dead weights
- Sink by prep repaired
- Reseal mop sink
- Second water filter (left untouched per direction)
- Deep clean walk-in cooler
- Prep sink chemical dispensing fixed
- Prep Table Replaced
- Declutter dish area

Roof
- Grease drip pipe (far right unit)
- Drain pipe cleared

General
- Drains jetted

Feb 4, 2026

FACILITIES UPDATE

ALTAMESA & MCCART FSU (02810)

IN PROGRESS

Outside
- Menu board flip function
- Menu board lights
- Big Altamesa sign
- Dumpster handles / door sticking

Dining Room
- Table replacement (on order)
- Booth seatback replacement (on order)
- Roller shades (on order)
- Door stops broken

Front Counter / DT
- Third drink tower (scheduled)
- All drink towers PM (scheduled with Coke)
- Menu board
- Electrical panels on floor
- Tiles need re-grouting

Playland
- Flooring
- Paint peeling on walls

Restrooms
- Baby changing station
- Button on women's restroom toilet

Office
- Ceiling hole
- Right-back wall hole

Back Area
- Cage door sweep
- Hole in wall

Kitchen
- Ceiling tiles dirty
- Oven knob (oven being removed)
- Fire safety (Ansul pull system part ordered)
- Add egg cookers
- Henny / grill PM
- Walk-in panic alarm key missing (on order)
- Light cover missing
- Freezer door side panel detached

Roof
- HVAC PM

Feb 4, 2026