



MV: <u>ENERGY INTEGRITY</u>	REF. NO.:	DATE: <u>4-05-2026</u>
IMO: <u>9859739</u>	LOA: <u>295m</u>	BEAM: <u>46m</u>
AGENT:	Tel:	BOW: <u>9,4m</u> AFT: <u>9,6m</u>

JOB ASSIGNMENT:**JOBS CARRIED OUT**

PHOTO INSPECTION
VIDEO INSPECTION
CLASS INSPECTION



PROPELLER POLISHING



V SIDES CLEANING



FLAT BOTTOM CLEANING

INTAKE GRIDS CLEANING



PROPELLER REPAIR



HULL REPAIRS



WELDING



CUTTING



OTHER: _____

WHEN:

DAYTIME:



NIGHT TIME



WEEKEND



HOLIDAYS



MOBILIZATION	DEPART FROM PORT	ALONGSIDE VESSEL
<u>12:30</u>	<u>13:30</u>	<u>14:10</u>

DEPART FROM VESSEL	RETURN TO PORT	DEMOBILIZATION
<u>1:30</u>	<u>2:30</u>	<u>3:30</u>

DIVING SUPPORT VESSEL	DSV CREW	DIVE TEAM
<u>LIBERTAD SEIS</u>	1. <u>JUAN</u>	1. <u>DAVID LLAVES</u>
	2.	2. <u>SOLAIMAN AMRANI</u>
	3.	3. <u>DAVID VAZQUEZ</u>
		4. <u>JONATHAN MACIAS</u>
		5. <u>ADRIAN GARCIA</u>
		6.

WORKS PERFORMED	START	END
1. <u>PHOTO INSPECTION</u>	<u>14:53</u>	<u>15:45</u>
2. <u>V-SIDES CLEANING</u>	<u>14:55</u>	<u>23:30</u>
3. <u>PROPELLER POLISHING X2</u>	<u>19:44</u>	<u>00:50</u>
4.		
5.		
6.		
7.		

REMARKS**MASTER SIGNATURE****VESSEL STAMP**