

GX 460 — Pre-Purchase Checklist

2019 Lexus GX 460 Premium / KDSS · VIN JTJBM7FX3K5218253 · seller claims ~70k mi · no tools, no crawling. History: 1-owner CA, no accidents, dealer-maintained to 51k. Photos: stock height, no lean.

0 · BEFORE YOU GO (5 min, at home)

- ☐ **Run VIN JTJBM7FX3K5218253 at [nhtsa.gov/recalls](https://www.nhtsa.gov/recalls)**
Expect 0 open recalls.
- ☐ **Ask seller: cold engine, flat parking spot, title in hand**

1 · STANCE & LEAN (3 min)

- ☐ **From 20 ft, dead-center front then rear: body even left/right, roof parallel to ground**
- ☐ **Fingers in tire-to-fender gap at all 4 wheels**
Left = right (± 1 finger); rear = front + 1. Driver side low at BOTH axles = KDSS lean, negotiate.
- ☐ **Push each corner down 3x: one rebound, then stops**
Keeps bobbing = worn shocks (height can still be perfect).

2 · KDSS LEAK PEEK (3 min · kneel + phone light)

- ☐ **Driver-side frame rail under front door: KDSS valve block dry — WALK IF BAD**
Dry dusty metal = OK. Wet shine / oily crust = leak, ~\$1-2k.
- ☐ **Front wheel wells: cylinder + lines at sway bar dry — WALK IF BAD**
- ☐ **Behind rear tires: rear cylinder dry — WALK IF BAD**
- ☐ **No fresh drip spots on pavement under truck**

3 · BODY & TIRES (4 min)

- ☐ **Panel gaps even; black paint matches panel-to-panel; no overspray on trim — WALK IF BAD**
Report says no accidents — this is the verify.
- ☐ **All 4 tires 265/60R18, same brand; even wear inner vs outer; no saw-tooth under palm**
- ☐ **Sidewall DOT date newer than ~2021**
Older = budget for tires.
- ☐ **Through wheel spokes: visible pad meat, no big rotor lip**

4 · ENGINE BAY (3 min)

- ☐ **Dipstick: amber to brown — WALK IF BAD**
Milky or glittery = walk away.
- ☐ **Coolant reservoir pink, at line; no white crust at radiator**
- ☐ **Brake fluid at line; belt uncracked; battery terminals clean**
Battery is from 4/2022 — due soon regardless.
- ☐ **No raw-fuel or burnt-oil smell**

5 · CABIN (4 min)

- ☐ **Odometer ~70k and wear matches (pedals, wheel, bolster) — WALK IF BAD**
Far off 70k = walk.
- ☐ **Start: all dash lights come on, then ALL go out (airbag, 4WD, check engine)**
- ☐ **AC ice cold; windows, sunroof, locks, mirrors, cameras; both fobs**
- ☐ **Side-swing rear door + glass hatch latch cleanly**
- ☐ **Fold 2nd/3rd rows; no musty smell or water stains**

6 · TEST DRIVE (15 min — never buy without it)

☐	Cold start: no rattle, no smoke
☐	Lot: full-lock circles both ways — no clicks or groans
☐	Slow figure-8, windows down — no clunks from corners
☐	Diagonal over driveway lip — no clunk Clunk = sway-bar / KDSS bushings or links.
☐	Speed bump: one settled motion, no float
☐	Straight road: wheel centered, no pull
☐	On-ramp sweep: stays flat That's KDSS working. Wallowy roll = system low.
☐	70 mph no shake · firm brake straight, no shudder · shifts smooth
☐	Lot: stop, shift N, twist knob to L4, feel it engage, back to H4

7 · PAPERWORK (5 min — clears the AutoCheck flags)

☐	Title is the NEW duplicate (issued ~6/29/2026) — why a duplicate? Loan paid off?
☐	If lien open: pay at their lender, get payoff + lien release — WALK IF BAD Never cash in the driveway. Refusal = walk.
☐	Seller photo ID matches name on title/registration — WALK IF BAD
☐	Any 2024-26 service receipts? Record goes silent after 50,942 mi (12/2023).
☐	Ask: 8/2023 "body service"? · 2022 re-lien a refi? · what did hitch tow? · why selling?
☐	Was the 60k service done anywhere?

VERDICT RULES

WALK: wet KDSS parts · milky oil · crash evidence · seller ≠ title name · won't do lender payoff · odometer far off 70k

NEGOTIATE: driver-side lean · old/worn tires · no records since 2023 · 60k service not done

BUY SIGNAL: everything clean — matches the strong photo and history read

Pocket reference: fender gaps left = right (± 1 finger), rear = front + 1 · last reported odometer 50,942 on 12/14/2023 (the 265,181 entry is a typo for 26,518) · fuel-pump recall likely done 4/2021, confirm by VIN · stock: 74.2" tall, 8.1" clearance, 265/60R18.