

Work order sheet

WO-1001 · Replace pump seal			
Asset: PUMP-001 Coolant pump		Assignee: Maria Lopez	
Status: In progress · Priority: High		Opened: 2026-09-01	

Step	Task	State	Hours
1	Drain coolant	Done	1.5
2	Remove old seal	Done	2.0
3	Fit new seal	Open	0.0
4	Test run	Open	0.0
Total hours:			3.5

WO-1002 · Quarterly HVAC service			
Asset: HVAC-002 Rooftop HVAC unit		Assignee: Priya Nair	
Status: Open · Priority: Normal		Opened: 2026-09-05	

Step	Task	State	Hours
1	Replace filters	Open	0.0
2	Check refrigerant	Open	0.0
3	Clean coils	Open	0.0
Total hours:			0

WO-1003 · Belt alignment			
Asset: CONV-003 Conveyor line 3		Assignee: Maria Lopez	
Status: Done · Priority: Normal		Opened: 2026-08-20	

Step	Task	State	Hours
1	Inspect belt	Done	1.0
2	Align pulleys	Done	2.5
Total hours:			3.5

WO-1004 · Load test generator			
Asset: GEN-004 Backup generator		Assignee: Tom Chen	
Status: Open · Priority: Urgent		Opened: 2026-09-10	

Step	Task	State	Hours
1	Run load bank	Open	0.0
2	Record readings	Open	0.0
Total hours:			0

WO-1005 · Vibration inspection			
Asset: PUMP-001 Coolant pump		Assignee: Unassigned	
Status: Open · Priority: Low		Opened: 2026-09-12	

Step	Task	State	Hours
	(no tasks)		0.0
Total hours:			0

All work orders: 7 hours

Technician signature: _____