

Location	Asset Sub-Type	Type/Material	Condition	Quantity	Comments
Office 4 (1st Floor)	Floor	Carpets	Good		
Office 4 (1st Floor)	Walls	Gyprock (Internal), Concrete (External)	Good		
Office 4 (1st Floor)	Ceiling	Mineral Fibre	Good		
Office 4 (1st Floor)	Lights	LED	Good	2	Working
Office 3 (1st Floor)	Floor	Carpets	Good		
Office 3 (1st Floor)	Walls	Gyprock (Internal), Concrete (External)	Good		
Office 3 (1st Floor)	Ceiling	Mineral Fibre	Good		
Office 3 (1st Floor)	Lights	LED	Good	2	Working
Office 2 (Ground Floor)	Floor	Tile	Good		
Office 2 (Ground Floor)	Walls	Gyprock (Internal), Concrete (External)	Good		
Office 2 (Ground Floor)	Ceiling	Mineral Fibre	Good		
Office 2 (Ground Floor)	Lights	LED	Good	2	1 light not working
Main Area	Floor	Tile	Good		
Main Area	Walls	Gyprock (Internal), Concrete (External)	Fair		
Main Area	Ceiling	Mineral Fibre	Good		
Main Area	Lights	LED	Good	4	Working
Reception	Floor	Tile	Good		
Reception	Walls	Gyprock (Internal), Concrete (External)	Good		
Reception	Ceiling	Mineral Fibre	Good		
Reception	Lights	LED	Good	2	Working
Reception	Joinery	Laminate / Laminate	Good		Wooden and Veneer benchtop for the reception

Location	Asset Sub-Type	Type/Material	Condition	Quantity	Comments
Server Room	Floor	Tile	Fair		
Server Room	Walls	Gyprock (Internal), Concrete (External)	Fair		
Server Room	Ceiling	Mineral Fibre	Good		
Server Room	Lights	LED	Good	1	Working
Main Area (1st Floor)	Floor	Carpets	Good		
Main Area (1st Floor)	Walls	Gyprock (Internal), Concrete (External)	Good		
Main Area (1st Floor)	Ceiling	Mineral Fibre	Good		
Main Area (1st Floor)	Lights	LED	Good	4	Working
Staircase	Floor	Carpets	Good		
Staircase	Walls	Gyprock (Internal), Concrete (External)	Good		
Staircase	Ceiling	Mineral Fibre	Good		
Staircase	Lights	LED	Good	1	Working
Staff Room	Floor	Tile	Good		
Staff Room	Walls	Gyprock (Internal), Concrete (External)	Fair		
Staff Room	Ceiling	Mineral Fibre	Good		
Staff Room	Lights	LED	Good	2	Working
Staff Room	Joinery	Laminate / Marble	Good		Marble top with Wooden cabinets
Storage Room	Floor	Tile	Good		
Storage Room	Walls	Gyprock (Internal), Concrete (External)	Good		
Storage Room	Ceiling	Mineral Fibre	Good		
Storage Room	Lights	LED	Good	1	Working

Location	Asset Sub-Type	Type/Material	Condition	Quantity	Comments
Storage Room	Joinery	Laminate	Good		Wooden Laminated Storage Cabinets
Female Bathroom / Toilets	Floor	Tile	Good		
Female Bathroom / Toilets	Walls	Concrete	Good		
Female Bathroom / Toilets	Ceiling	Mineral Fibre	Good		
Female Bathroom / Toilets	Lights	LED	Good	1	Working
Female Bathroom / Toilets	Joinery	Laminate	Good		Steel Framed Wooden bench
Office 1 (Ground Floor)	Floor	Tile	Good		
Office 1 (Ground Floor)	Walls	Gyprock (Internal), Concrete (External)	Good		
Office 1 (Ground Floor)	Ceiling	Mineral Fibre	Good		
Office 1 (Ground Floor)	Lights	LED	Good	2	Working
Male Bathroom / Toilets	Floor	Tile	Good		
Male Bathroom / Toilets	Walls	Concrete	Good		
Male Bathroom / Toilets	Ceiling	Mineral Fibre	Good		
Male Bathroom / Toilets	Lights	LED	Good	1	Working
Guard Room	Floor	Tile	Good		
Guard Room	Walls	Concrete	Fair		Surface wear and tear and paint chipping observed
Guard Room	Ceiling	Mineral Fibre	Fair		
Guard Room	Lights	LED	Good	1	Working
Yard Shed	Floor	Concrete	Fair		
Yard Shed	Walls	Steel	Fair		General wear and tear observed
Yard Shed	Ceiling	Mineral Fibre	Fair		General wear and tear observed

Location	Asset Sub-Type	Type/Material	Condition	Quantity	Comments
Yard Shed	Lights	Halogen	Fair	12	11 working, 1 not working
Male Toilet (Rear)	Floor	Tile	Fair		
Male Toilet (Rear)	Walls	Concrete	Fair		Paint peeling off the walls in some areas
Male Toilet (Rear)	Ceiling	Mineral Fibre	Fair		
Male Toilet (Rear)	Lights	LED	Good	2	Working
Female Toilet (Rear)	Floor	Tile	Good		
Female Toilet (Rear)	Walls	Concrete	Fair		
Female Toilet (Rear)	Ceiling	Mineral Fibre	Good		
Female Toilet (Rear)	Lights	LED	Good	1	Working

Location	Asset Sub-Type	Door Type	Door Frame Type	Condition	Door Closer	Door Jams Fitted	Door is Compliant	Lockable
Bathroom / Toilets	Doors	Timber Hinged Internal	Timber	Good	yes	yes	yes	yes
Bathroom / Toilets	Doors	Timber Hinged Internal	Steel	Good	yes	yes	yes	yes
Female Toilet (Rear)	Doors	Timber Hinged External	Timber	Good	yes	yes	yes	yes
Guard Room	Doors	Glass Hinged	Timber	Good	yes	yes	yes	yes
Male Toilet (Rear)	Doors	Timber Hinged Internal	Timber	Fair	yes	yes	yes	yes
Male Toilet (Rear)	Doors	Timber Hinged External	Timber	Good	yes	yes	yes	yes
Office 1 (Ground Floor)	Doors	Timber Hinged Internal	Timber	Good	yes	yes	yes	yes
Office 2 (Ground Floor)	Doors	Timber Hinged Internal	Timber	Good	yes	yes	yes	yes
Office 3 (1st Floor)	Doors	Timber Hinged Internal	Timber	Good	yes	yes	yes	yes
Office 4 (1st Floor)	Doors	Timber Hinged Internal	Timber	Good	yes	yes	yes	yes
Reception	Doors	Aluminium Hinged	Steel	Good	yes	yes	yes	yes
Server Room	Doors	Timber Hinged Internal	Timber	Good	yes	yes	yes	yes
Staff Room	Doors	Timber Hinged Internal	Timber	Good	yes	yes	yes	no
Staff Room	Doors	Aluminium Hinged	Steel	Good	yes	yes	yes	yes
Storage Room	Doors	Timber Hinged Internal	Timber	Good	yes	yes	yes	yes

Location	Asset Sub-Type	Comment	Condition	Last Test Result	Last Test Date
External	Distribution Board	Operational	Good	No Record	No Record
Server Room	Miscellaneous Electrical Boxes	Operational	Good	No Record	No Record
External	Switchboards	Decommissioned	Very Poor	No Record	No Record
External	Switchboards	Decommissioned	Very Poor	No Record	No Record
External	Switchboards	Decommissioned	Good	No Record	No Record
Main Area	Switchboards	Operational	Good	No Record	No Record

Location	Asset Sub-Type	Comment	Condition
External (Office and Carpark)	Smoking Area Structure (rear office)	Minor corrosion of flooring surface and bench connections.	Fair
External (Office and Carpark)	Water Tanks		Good
External (Office and Carpark)	Window s		Good
External (Office and Carpark)	Staff Carpark	Asphalt finish in generally good condition.	Good
External (Office and Carpark)	Kerbing		Good
External (Office and Carpark)	Linemarking	Generally faded in most areas. To be renewed in April 2026.	Fair
External (Office and Carpark)	Entrance Cabin		Good
External (Office and Carpark)	Wheel stops		Good
External (Yard)	Asphalt	Overall in good condition, areas of surface crushing due to long term weights of shipping containers	Good
External (Yard)	Linemarking	Generally faded in most areas. To be renewed in April 2026.	Poor
External (Yard)	Bollards	Generally in fair condition, in many instances grout around the bases have cracked and are deteriorating. Many of the bollard rag bolts need to be tightened.	Fair
External (Yard)	Fencing and Gates	Generally in good condition. No significant defects observed.	Good
External (Yard)	Drainage Grates	Generally in good condition.	Good
External (Yard)	Lighting	All 19 working, globes recently replaced October 2025. 2 light poles are to be transferred to another company.	Good
External (Yard)	Removal of Site Assets	Includes fencing, lighting, fire hydrants within zoning taken over by another company/authority	N/A

[illegible]

Location	Asset Sub-Type	Gate/Fencing Type	Condition	Comments
External	Gates	Steel Mesh Fencing	Good	Working
External	Gates	Rotating Steel Gate (Single Person)	Good	Working

Location	Asset Sub-Type	Condition	Last Test Result	Last Test Date	Comment
Bathroom / Toilets	Ceiling Exhaust Fans	Good	No Record	No Record	Working
Bathroom / Toilets	Ceiling Exhaust Fans	Good	No Record	No Record	Working
Female Toilet (Rear)	Ceiling Exhaust Fans	Good	No Record	No Record	Working
Male Toilet (Rear)	Ceiling Exhaust Fans	Good	No Record	No Record	Working
Guard Room	Reverse Cycle / Split System	Good	No Record	No Record	Working
Main Area (1st Floor)	Reverse Cycle / Split System	Good	No Record	No Record	Working
Main Area	Reverse Cycle / Split System	Good	No Record	No Record	Working
Office 1 (Ground Floor)	Reverse Cycle / Split System	Good	No Record	No Record	Working
Office 3 (1st Floor)	Reverse Cycle / Split System	Good	No Record	No Record	Working
Office 4 (1st Floor)	Reverse Cycle / Split System	Good	No Record	No Record	Working
Server Room	Reverse Cycle / Split System	Good	No Record	No Record	Working
Staff Room	Reverse Cycle / Split System	Good	No Record	No Record	Working

Location	Asset Sub-Type	Condition	Last Test Result	Last Test Date	Comment
External (Office)	Hot Water Unit	Good	No Record	No Record	Working
External (Office)	Oily Water Seperator	Good	No Record	No Record	Working

Location	Asset Sub-Type	Condition	Last Test Result	Last Test Date	Comment
External (Office)	Security Alarm System	Good	No Record	No Record	Working

Location	Asset Sub-Type	Condition	Last Test Result	Last Test Date	Comment
Main Area	Defibrillator	Good	No Record	No Record	Unknown if working